PDF inspection copy converted with LibreOffice Writer Web. Image overlays are flattened for this PDF display only; original media and separate annotation data remain unchanged in the source HTML/manifest. This is not a macOS Quartz re-export.

FORMA RECAP · SYNTHETIC DEMO

Element evidence and reconciliation packet

Northbank Research Center · Level 02 · Ductwork · East wing · supply air

Model fixture-model / fixture-model-v7

Generated 2026-10-19T18:05:27.729Z · fixture-reviewer
Packet packet-425f85fd-8739-4abe-a90f-2ac0943491d8 · snapshot SHA-256 2eb4d3106a4fa21d64432fcb46b66393af4ded56e137e47dc1c3c13d87d48138

Synthetic demonstration evidence only. Human observations do not establish inspection acceptance, measured installation quantities, contractual completion, or payment approval. “Not observed” does not mean absent, incomplete, or zero. Manual location associations are not verified 3D registration.

Individual element findings

Element	Evidence date	Observation	Rationale and uncertainty	Review
DUCT-01	fixture-capture-01 2026-10-08 (date)	Observed installed Evidence usable	Acceptance example: the main supply duct is visible in the synthetic October 8 illustration. This bounded human observation does not measure quantity or establish acceptance.	fixture-reviewer 2026-10-19T18:01:49.435Z Revision 1
DUCT-03	fixture-capture-01	Needs review	Acceptance example: the relevant	fixture-reviewer

Element	Evidence date	Observation	Rationale and uncertainty	Review
	2026-10-08 (date)	Evidence limited	terminal connection is obscured in this synthetic capture; no installed or absent state can be established. A close-up from below must show the coupling and terminal neck before ceiling closure.	2026-10-19T18:02:00.526Z Revision 1
DUCT-03	photo-6026f353-e121-4a89-9896-d9e6c51e5a49 2026-10-18T09:30:00-04:00 (timestamp)	Observed installed Evidence usable	Acceptance example: the synthetic follow-up shows the terminal coupling and neck. This reviewer records observed installed for the illustrated element only; no inspection or quantity approval is inferred. Hidden fasteners, seal integrity and inspection acceptance are not established by this view.	fixture-reviewer 2026-10-19T18:03:43.994Z Revision 1

Coverage

Unique selected elements: 3. {"usable":1,"unresolved":0,"outdated":1,"no_evidence":1,"date_unknown":0}. Freshness 7 days as of 2026-10-19. This is evidence coverage, not percent installed or complete. Evidence older than the configured number of calendar days is outdated; unknown dates cannot establish freshness. Unassessed elements remain explicitly without individual findings.

Element	Coverage state	Finding / capture / date	Basis
DUCT-01 Main supply duct	outdated	finding-revision-981836e7-f51a-44d4-bb5f-26fde4ad172a fixture-capture-01 2026-10-08	Latest usable reviewed evidence exceeds the configured freshness rule.

Element	Coverage state	Finding / capture / date	Basis
DUCT-02 East branch duct	no evidence	Unassessed No individual evidence Unknown	No individual element finding; historical scope reviews do not establish element coverage.
DUCT-03 Terminal connection	usable	finding-revision-49e6abf5-86cd-4c48-8a28-22082e61ef09 photo-6026f353-e121-4a89-9896-d9e6c51e5a49 2026-10-18	Reviewer marked dated evidence usable; this is evidence coverage, not installation quantity.

Recapture tasks

Element / status	Uncertainty / viewpoint	Responsibility	Preserved references
DUCT-03 Capture request: completed Review: reassessed	A close-up from below must show the coupling and terminal neck before ceiling closure. Required: Close-up from below showing the terminal coupling and neck before ceiling closure.	Mechanical supervisor — synthetic pilot Due 2026-10-20 Before concealment 2026-10-21	Origin finding finding-revision-79068110-da0d-4efa-aae9-32b28645fd33 Origin capture fixture-capture-01 Model fixture-model / fixture-model-v7 New capture photo-6026f353-e121-4a89-9896-d9e6c51e5a49 Evidence supplied 2026-10-19T18:03:12.275Z Reassessment finding-revision-49e6abf5-86cd-4c48-8a28-22082e61ef09

Progress reconciliation

Manual reported information, imagery-supported quantities, unresolved scope, inspection decisions and recorded approvals remain separate. Unknown quantities remain unknown; comparable differences require matching units, scope, period and basis.

Category	Quantity	Scope / period	Source and basis
trade_reported	12 m	2026-10-01 to 2026-10-19 DUCT-01	Source: docs/DEMO-MEASUREMENTS.md#DEMO-R1 (synthetic) Basis: Authored manual test statement of centerline length; not a site measurement. Method: manual_measurement
imagery_supported	9 m	2026-10-01 to 2026-10-19 DUCT-01	Source: docs/DEMO-MEASUREMENTS.md#DEMO-M1 (synthetic) Basis: Authored manual review-sheet value for reconciliation testing; not estimated from image pixels or review counts. Method: manual_measurement
unresolved	Unknown m	2026-10-01 to 2026-10-19 DUCT-02	Source: docs/DEMO-MEASUREMENTS.md#DEMO-G1 (synthetic) Basis: No individual finding or measured quantity supplied; unknown remains unknown. Method: manual_measurement
inspection	Unknown m	2026-10-01 to 2026-10-19 DUCT-03	Source: docs/DEMO-MEASUREMENTS.md#DEMO-I1 (synthetic) Basis: No inspection/acceptance record supplied; illustrated visibility is insufficient. Method: manual_measurement
approved	Unknown m	2026-10-01 to 2026-10-19 DUCT-01	Source: docs/DEMO-MEASUREMENTS.md#DEMO-A1 (synthetic)

Category	Quantity	Scope / period	Source and basis
			Basis: No authorized approver or approval reference supplied; quantity remains unknown. Method: manual_measurement

Reporting period: All recorded periods. Each quantity comparison retains its own reporting period.

Reported versus imagery-supported quantities

Scope / period	Trade reported	Imagery supported	Reported minus supported	Comparison basis
DUCT-01 2026-10-01 to 2026-10-19	12 m	9 m	3 m	Comparable manual records Reported minus imagery-supported manual quantity, using matching unit, exact elements, period, method, and comparison basis.

Reviewed element observations

3 selected elements · 2 observed installed · 0 not observed · 0 needs review · 1 without an individual finding · 0 with unknown capture dates · 0 with conflicting observations. Each element appears once across capture dates. These are observation counts, separate from evidence coverage, installed quantities, and percent complete.

Element	Reviewed observation	Evidence date / capture	Review basis
DUCT-01 Main supply duct	Observed installed Evidence usable	2026-10-08 fixture-capture-01	Latest explicitly dated element observation; counted once across capture dates.
DUCT-02 East branch duct	no finding	Unknown	No individual element finding; historical scope assessments are not expanded.
DUCT-03 Terminal connection	Observed installed Evidence usable	2026-10-18 photo-6026f353-e121-4a89-9896-d9e6c51e5a49	Latest explicitly dated element observation; counted once across capture dates.

Completion calculation basis

Percentages require an explicit positive denominator and a supported manual quantity method with matching unit and exact scope. Unknown or incomparable values remain unknown. Visibility alone does not establish inspection acceptance, contractual completion, or payment approval.

Manual record / scope	Recorded quantity	Explicit denominator	Completion	Basis / limitation
trade reported · docs/DEMO-MEASUREMENTS.md#DEMO-R1 (synthetic) DUCT-01	12 m	Not provided	Unknown	Completion percentages are limited to manually supported or approved quantity records.
imagery supported · docs/DEMO-MEASUREMENTS.md#DEMO-M1 (synthetic) DUCT-01	9 m	Not provided	Unknown	No explicit positive denominator was provided.
unresolved · docs/DEMO-MEASUREMENTS.md#DEMO-G1 (synthetic)	Unknown m	Not provided	Unknown	The numerator is unknown.

Manual record / scope	Recorded quantity	Explicit denominator	Completion	Basis / limitation
DUCT-02				
inspection · docs/DEMO-MEASUREMENTS.md#DEMO-I1 (synthetic) DUCT-03	Unknown m	Not provided	Unknown	The numerator is unknown.
approved · docs/DEMO-MEASUREMENTS.md#DEMO-A1 (synthetic) DUCT-01	Unknown m	Not provided	Unknown	The numerator is unknown.

Local Issue and RFI drafts


RFI: Confirm terminal clearance and inspection requirements

Synthetic acceptance example: the October 8 connection was obscured. The October 18 imported test view now shows the coupling, but clearance criteria, hidden fixings and inspection acceptance remain unverified. Selected original and follow-up findings are retained below.

Location Level 02 · East wing · DUCT-03 terminal · Requested action Confirm the required clearance, accepting inspector and inspection criteria before ceiling closure. Identify any additional evidence required; visible installation alone is not acceptance. · Proposed assignee MEP design coordinator — synthetic pilot

Finding revisions finding-revision-49e6abf5-86cd-4c48-8a28-22082e61ef09, finding-revision-79068110-da0d-4efa-aae9-32b28645fd33

Synthetic test recapture · Terminal close-up · October 18



Exact finding revision finding-revision-49e6abf5-86cd-4c48-8a28-22082e61ef09

Model fixture-model / fixture-model-v7 · element DUCT-03

Capture photo-6026f353-e121-4a89-9896-d9e6c51e5a49 · 2026-10-18T09:30:00-04:00 (timestamp) · uploaded 2026-10-19T18:02:59.591Z

Source Bundled synthetic recapture PNG; test pixels, not field evidence.

SHA-256 47030eb7dd374cc09c5312ae64b8dfe1a323b928160a086c242c1ec796470ba0

Selected annotations: annotation-fff902f7-7644-46e3-bb87-50a2dee9aeab. These overlays retain this draft's selected historical finding revision.

East corridor · October 8



Exact finding revision finding-revision-79068110-da0d-4efa-aae9-32b28645fd33

Model fixture-model / fixture-model-v7 · element DUCT-03

Capture fixture-capture-01 · 2026-10-08 (date) · uploaded 2026-10-09T14:05:00Z

Source Synthetic SVG illustration; no customer imagery, actual site observation, or camera pose.

SHA-256 ffa399e8aea72b4e349e7173031783447ccf660f2ce3d2b65f119a4f28fd6948

Selected annotations: annotation-b51b1cfc-8bff-42ad-aa4b-ae0c6346a3d0. These overlays retain this draft’s selected historical finding revision.

Local editable draft only. External submission disabled; no external record created.

Original evidence with separate annotations

East corridor · October 8



fixture-capture-01 · Original SHA-256 ffa399e8aea72b4e349e7173031783447ccf660f2ce3d2b65f119a4f28fd6948

Display trusted_svg_lossless_png · SHA-256 74c59d889375db30190f071b0bcb7bd6d47a233b2016f4c9e3d899fe68aae206

Capture 2026-10-08 (date) · uploaded 2026-10-09T14:05:00Z

Source Synthetic SVG illustration; no customer imagery, actual site observation, or camera pose.. Annotation overlays are separate from unchanged original bytes.

Display derivatives are embedded separately with their original-source hash.

East corridor · October 15



fixture-capture-02 · Original SHA-256 f2ab815a5935b7e2e90956d932c9797e3e4e3a8e13db2a212a03e718a74656c8

Display trusted_svg_lossless_png · SHA-256 8c1e9e567f0d89f64027e7d9a7c0c34e407912aa02c8f6f4298d0583c4e78aa0

Capture 2026-10-15T10:20:00-04:00 (timestamp) · uploaded 2026-10-16T14:00:00Z

Source Synthetic SVG illustration; no customer imagery, actual site observation, or camera pose.. Annotation overlays are separate from unchanged original bytes. Display derivatives are embedded separately with their original-source hash.

Synthetic test recapture · Terminal close-up · October 18





photo-6026f353-e121-4a89-9896-d9e6c51e5a49 · Original SHA-256 47030eb7dd374cc09c5312ae64b8dfe1a323b928160a086c242c1ec796470ba0

Display original_raster · SHA-256 47030eb7dd374cc09c5312ae64b8dfe1a323b928160a086c242c1ec796470ba0

Capture 2026-10-18T09:30:00-04:00 (timestamp) · uploaded 2026-10-19T18:02:59.591Z

Source Bundled synthetic recapture PNG; test pixels, not field evidence.. Annotation overlays are separate from unchanged original bytes. Display derivatives are embedded separately with their original-source hash.

Reference plan



fixture-plan · Original SHA-256 b654f972a7bfb2ab7beb6e44ea3414cea4f9a564ef315a543f384cbc539b46d0

Display trusted_svg_lossless_png · SHA-256 fc1a183f18051035ae9998d953b280dc03caf2acb91012341d70d9b36ef737cb

Capture Unknown (reference plan) · uploaded not applicable

Source Synthetic reference plan. Annotation overlays are separate from unchanged original bytes. Display derivatives are embedded separately with their original-source hash.

Individual finding revision history

DUCT-01 · revision 1 · Observed installed

Acceptance example: the main supply duct is visible in the synthetic October 8 illustration. This bounded human observation does not measure quantity or establish

acceptance.
Uncertainty: None recorded · Evidence quality: usable

Finding finding-f66ce1c6-a031-4835-90a7-21a2fa7f02ae
Revision finding-revision-981836e7-f51a-44d4-bb5f-26fde4ad172a
Previous revision none
Model fixture-model / fixture-model-v7 · Scope fixture-scope revision 1
Capture fixture-capture-01 · 2026-10-08 (date) · uploaded 2026-10-09T14:05:00Z
Reviewer fixture-reviewer (synthetic_demo) · assessed 2026-10-19T18:01:49.435Z


No region annotation saved for this revision.

Annotation IDs: none. Original media remains separate from annotation data.

DUCT-03 · revision 1 · Needs review

Acceptance example: the relevant terminal connection is obscured in this synthetic capture; no installed or absent state can be established.
Uncertainty: A close-up from below must show the coupling and terminal neck before ceiling closure. · Evidence quality: limited

Finding finding-57201ffb-791d-42e3-8f1a-26c27f2270e6
Revision finding-revision-79068110-da0d-4efa-aae9-32b28645fd33
Previous revision none
Model fixture-model / fixture-model-v7 · Scope fixture-scope revision 1
Capture fixture-capture-01 · 2026-10-08 (date) · uploaded 2026-10-09T14:05:00Z
Reviewer fixture-reviewer (synthetic_demo) · assessed 2026-10-19T18:02:00.526Z



Annotation IDs: annotation-b51b1cfc-8bff-42ad-aa4b-ae0c6346a3d0. Original media remains separate from annotation data.

DUCT-03 · revision 1 · Observed installed


Acceptance example: the synthetic follow-up shows the terminal coupling and neck. This reviewer records observed installed for the illustrated element only; no inspection or quantity approval is inferred.
Uncertainty: Hidden fasteners, seal integrity and inspection acceptance are not established by this view. · Evidence quality: usable

Finding finding-da9d0ade-7cb5-4e7a-8cd6-7dfe7f3418a8
Revision finding-revision-49e6abf5-86cd-4c48-8a28-22082e61ef09
Previous revision none
Model fixture-model / fixture-model-v7 · Scope fixture-scope revision 1
Capture photo-6026f353-e121-4a89-9896-d9e6c51e5a49 · 2026-10-18T09:30:00-04:00 (timestamp) · uploaded 2026-10-19T18:02:59.591Z
Reviewer fixture-reviewer (synthetic_demo) · assessed 2026-10-19T18:03:43.994Z

Explicit reassessment for task recapture-b195736c-8900-4558-af18-06aa310f45ec

Origin finding revision finding-revision-79068110-da0d-4efa-aae9-32b28645fd33

Origin capture fixture-capture-01 · model fixture-model / fixture-model-v7. Original finding and evidence references remain unchanged.



Annotation IDs: annotation-fff902f7-7644-46e3-bb87-50a2dee9aeab. Original media remains separate from annotation data.

Recapture decision history

Completing a capture request records evidence supplied. It does not assign an installation state, inspection acceptance, quantity approval or payment decision.

Task / event	When / reviewer	Preserved links	Capture and review status
recapture-b195736c-8900-4558-af18-06aa310f45ec created	2026-10-19T18:02:31.694Z fixture-reviewer	Origin finding-revision-79068110-da0d-4efa-aae9-32b28645fd33 New capture none Assessment pending	Capture request: requested Review: pending_evidence
recapture-b195736c-8900-4558-af18-06aa310f45ec evidence_linked	2026-10-19T18:03:12.275Z fixture-reviewer	Origin finding-revision-79068110-da0d-4efa-aae9-32b28645fd33 New capture photo-6026f353-e121-4a89-9896-d9e6c51e5a49 Assessment pending	Capture request: completed Review: awaiting_reassessment
recapture-b195736c-8900-4558-af18-06aa310f45ec reassessed_and_closed	2026-10-19T18:03:43.995Z fixture-reviewer	Origin finding-revision-79068110-da0d-4efa-aae9-32b28645fd33 New capture photo-6026f353-e121-4a89-9896-d9e6c51e5a49 Assessment finding-revision-49e6abf5-86cd-4c48-8a28-22082e61ef09	Capture request: completed Review: reassessed

Historical scope assessments

Preserved scope-level records are separate from individual element findings. Their states do not establish findings for every associated element.

Record / revision	Capture / model / scope	Historical assessment	Reviewer / time
Historical scope assessment assessment-c42c837d-b1b3-48a2-81a4-1ebf95316817 Revision 1 revision-aecd4dd9-602c-428f-8cfd-6592d03f2b04	fixture-capture-01 fixture-model-v7 Scope fixture-scope	Not observed in reviewed evidence Synthetic walkthrough: the terminal connection is not observed in the October 8 illustration. This finding concerns visible evidence only. The view does not show the terminal connection; absence and installation timing	fixture-reviewer 2026-10-19T15:51:46.501Z

Record / revision	Capture / model / scope	Historical assessment	Reviewer / time
		cannot be inferred.	
Historical scope assessment assessment-6a5a754a-312a-4f0b-9fcd-e19a9724d7f9 Revision 1 revision-535b5c3e-8d2a-4a1c-8982-cfd7d963c775	fixture-capture-02 fixture-model-v7 Scope fixture-scope	Observed installed Synthetic walkthrough: the visible supply duct is present in the October 15 illustration. This is a reviewer observation only.	fixture-reviewer 2026-10-19T15:50:54.863Z
Historical scope assessment assessment-6a5a754a-312a-4f0b-9fcd-e19a9724d7f9 Revision 2 revision-820c8f6b-ee5d-453b-9527-035ff1183337	fixture-capture-02 fixture-model-v7 Scope fixture-scope	Needs review Correction: the synthetic illustration does not resolve the terminal connection. Keep the visible duct observation bounded and request review. Terminal connection is occluded; no installed quantity or acceptance is inferred.	fixture-reviewer 2026-10-19T15:51:07.035Z

Revision and placement history

3 immutable element finding revisions; 3 task events; 3 historical scope assessment revisions. Historical scope records are not converted into per-element findings.