

**INFINITI USA**  
One Nissan Way  
Franklin, TN 37067  
[www.infinitiusa.com](http://www.infinitiusa.com)

---

**TO: COLLISION REPAIR INDUSTRY**

**POSITION STATEMENT: Calibration of Around View® Monitor/ September 15, 2016/  
Reference: IPSB-16-395**

FRANKLIN, TN– Many INFINITI vehicles are now being equipped with Around View® Monitor systems, which incorporate the use of cameras in front, rear, and both sides of the vehicle.

INFINITI has taken the position that any time a camera, or camera mounting part (front grille, door mirror, or others) is removed, installed, or replaced, it is **mandatory** for the qualified repair professional to perform a calibration of this system.

Failure to adhere to this calibration procedure could result in the Around View® Monitor system not functioning as originally intended. We ask that the general repair industry adhere to these guidelines immediately.

Reference service manual section "AV" for additional information.

**Parts Warranty**

INFINITI's New Vehicle Limited Warranty, and Limited Warranty on replacement parts do not apply to any parts other than genuine original equipment parts.

INFINITI will not be responsible for any subsequent repair costs associated with a vehicle and/or part failure caused by the use of parts other than genuine replacement parts.

For additional collision information: <http://infiniticollisionnetwork.com>

