COMPONENTS USED:

1. **Servo Motors x 3:** To achieve accurate, step-by-step movement using PWM, giving more control to the user.
2. **DC Motor x 1:** For single-direction continuous rotation required for the obstacle.
3. **Push Buttons x 3:** To have three different achievable speeds for the DC Motor, using the two values 1 and 0, which it produces on complete and incomplete circuit loops.
4. **ESP32:** The main device, which is the microcontroller performing the coded operations.
5. **Power Supply Module:** Provides the connection to the ESP32 from the socket for a 5-volt supply.
6. **Motor Driver:** A component connected between the DC Motor and the Power Supply/ESP32 for control, such as modifiable duty cycles, directional change, etc.
7. **Power Adapter:** Connects the Power Supply Module to the socket.
8. **Female Jack:** Connected to the Motor Driver and the Male Jack, which brings in voltage from the Power Adapter.
9. **Male Jack:** Connects all components working through the Power Supply Module to the Female Jack, to obtain voltage.