



USERS GUIDE

Radiant QuikLog

Equipment master and calibration tracker for the QA program.

QuikLog
RADIANT MEDICAL PHYSICS CONSULTING

Inventory + Add Asset Inventory Report Due Soon LOCAL-FIRST - SQLITE

Activate Radiant QuikLog

Radiant QuikLog requires a license key to run. Paste your `RADKEY-...` key below to activate this install.

LICENSE KEY — the full key, with or without dashes

`RADKEY-XXXXXX-XXXXXX-...`

ACTIVATE QUIKLOG

Radiant QuikLog verifies license keys entirely offline. No information leaves this server. Need a key? Contact Radiant Medical Physics Consulting.

Radiant QuikLog — a tool of Radiant Medical Physics Consulting LLC. Runs 100% locally; no data leaves this machine. Calibration warning thresholds must be reviewed and approved by a Qualified Medical Physicist or Radiation Safety Officer.

OVERVIEW

What QuikLog is.

Radiant QuikLog is an equipment master and calibration tracker for radiation oncology — linacs, CT simulators, HDR units, ion chambers, electrometers, well chambers, and survey meters, in one local inventory sorted by what's due first.

The single source of truth

Every piece of QA-relevant equipment lives in one searchable list, with serial numbers, manufacturers, install dates, and the full calibration history per asset. Color-coded due-soon and overdue badges put attention exactly where it's needed.

Who it's for

- Clinical physicists and QA programs.
- Equipment masters for state inspections and J-CAHO visits.
- ADCL coordination and chamber-bank management.

QuikLog
RADIANT MEDICAL PHYSICS CONSULTING

Inventory + Add Asset Inventory Report Due Soon LOCAL-FIRST · SQLITE

Activate Radiant QuikLog

Radiant QuikLog requires a license key to run. Paste your `RADKEY-~` key below to activate this install.

LICENSE KEY — the full key, with or without dashes

RADKEY-XXXXXX-XXXXXX-~

ACTIVATE QUIKLOG

Radiant QuikLog verifies license keys entirely offline. No information leaves this server. Need a key? Contact Radiant Medical Physics Consulting.

Radiant QuikLog — a tool of Radiant Medical Physics Consulting LLC. Runs 100% locally; no data leaves this machine. Calibration warning thresholds must be reviewed and approved by a Qualified Medical Physicist or Radiation Safety Officer.

ASSET LIST — DUE-SOON AND OVERDUE FRONT-AND-CENTER.

Open QuikLog, add your first asset.

Access

QuikLog is deployed at quiklog.radiant-mpc.com. Open the URL in any modern browser. There is nothing to install on the workstation.

Sign-in

QuikLog uses a per-instance access password supplied with your agreement. Enter the password once and the session persists in the browser.

Add an asset

1. From the dashboard, click *+ New Asset*.
2. Set the asset type — Linac, CT Sim, HDR, Ion Chamber, Electrometer, Well Chamber, Survey Meter, or Other.
3. Fill in manufacturer, model, serial number, location, install date, and the recurring calibration interval.
4. Save. The asset appears on the dashboard with its first next-due date.

QuikLog
RADIANT MEDICAL PHYSICS CONSULTING

Inventory + Add Asset Inventory Report Due Soon LOCAL-FIRST · SQLITE

Activate Radiant QuikLog

Radiant QuikLog requires a license key to run. Paste your **RADKEY-...** key below to activate this install.

LICENSE KEY — the full key, with or without dashes

RADKEY-XXXXXX-XXXXXX-...

ACTIVATE QUIKLOG

Radiant QuikLog verifies license keys entirely offline. No information leaves this server. Need a key? Contact Radiant Medical Physics Consulting.

Radiant QuikLog — a tool of Radiant Medical Physics Consulting LLC. Runs 100% locally; no data leaves this machine. Calibration warning thresholds must be reviewed and approved by a Qualified Medical Physicist or Radiation Safety Officer.

ASSET DETAIL — CALIBRATION HISTORY AND NEXT-DUE.

1. Open the asset, click *+ Log calibration*.
2. Enter the calibration date, the next-due date (defaults from interval), the performer, and the ADCL or vendor certificate number.
3. Attach the certificate PDF if you have one — it travels with the event in subsequent reports.
4. Save. The event joins the asset's calibration ledger, and the asset's next-due date updates automatically.

QuikLog
RADIANT MEDICAL PHYSICS CONSULTING

[Inventory](#) [+ Add Asset](#) [Inventory Report](#) [Due Soon](#) LOCAL-FIRST · SQLITE

Radiant QuikLog requires a license key to run. Paste your **RADKEY-...** key below to activate this install.

LICENSE KEY — the full key, with or without dashes

RADKEY-XXXXXX-XXXXXX-...

ACTIVATE QUIKLOG

Radiant QuikLog verifies license keys entirely offline. No information leaves this server. Need a key? Contact Radiant Medical Physics Consulting.

Radiant QuikLog — a tool of Radiant Medical Physics Consulting LLC. Runs 100% locally; no data leaves this machine. Calibration warning thresholds must be reviewed and approved by a Qualified Medical Physicist or Radiation Safety Officer.

NEW CALIBRATION EVENT – DATE, PERFORMER, ADCL NUMBER, CERTIFICATE UPLOAD.

The due-soon dashboard.

The due-soon report is the daily-glance view: every asset whose next-due date falls in the next N days, sorted soonest-first. The default window is 60 days; adjust with the *days* filter.

- Red rows are **overdue**.
- Amber rows are **due within 14 days**.
- Yellow rows are **due within 30 days**.

The dashboard is the right view for the start of a QA week — everything that needs attention is on one screen, with a one-click hop into the asset to log the cal once it's done.

QuikLog
RADIANT MEDICAL PHYSICS CONSULTING

Inventory + Add Asset Inventory Report Due Soon LOCAL-FIRST · SQLITE

Activate Radiant QuikLog

Radiant QuikLog requires a license key to run. Paste your `RADKEY-...` key below to activate this install.

LICENSE KEY — the full key, with or without dashes

RADKEY-XXXXXX-XXXXXX-...

ACTIVATE QUIKLOG

Radiant QuikLog verifies license keys entirely offline. No information leaves this server. Need a key? Contact Radiant Medical Physics Consulting.

Radiant QuikLog — a tool of Radiant Medical Physics Consulting LLC. Runs 100% locally; no data leaves this machine. Calibration warning thresholds must be reviewed and approved by a Qualified Medical Physicist or Radiation Safety Officer.

DUE-SOON REPORT — COLOR-CODED BY URGENCY WINDOW.

Printable inventory + due-soon PDFs.

Two reports cover the binder side of the workflow.

Full inventory PDF

The complete asset master with serial numbers, location, calibration status, and next-due — formatted for the QA binder and for handing to state inspectors.

Due-soon PDF

The filtered list for the next N days, ready for the cal-week huddle.

Both reports inherit your practice name and any logo you uploaded in *Settings*.

QuikLog
RADIANT MEDICAL PHYSICS CONSULTING

Inventory + Add Asset Inventory Report Due Soon LOCAL-FIRST · SQLite

Activate Radiant QuikLog

Radiant QuikLog requires a license key to run. Paste your `RADKEY-...` key below to activate this install.

LICENSE KEY — the full key, with or without dashes

RADKEY-XXXXXX-XXXXXX-...

ACTIVATE QUIKLOG

Radiant QuikLog verifies license keys entirely offline. No information leaves this server. Need a key? Contact Radiant Medical Physics Consulting.

Radiant QuikLog — a tool of Radiant Medical Physics Consulting LLC. Runs 100% locally; no data leaves this machine. Calibration warning thresholds must be reviewed and approved by a Qualified Medical Physicist or Radiation Safety Officer.

INVENTORY REPORT — PRINTABLE PDF.

License, safety, and how to reach us.

License terms

QuikLog is licensed per practice. The deployed instance at quiklog.radiant-mpc.com is provided as a hosted evaluation; a self-hosted on-prem build is available on request.

Privacy

QuikLog stores equipment master data only — no patient identifiers and no PHI. Calibration certificate attachments are stored in the application's data directory.

Contact

Live URL: <https://quiklog.radiant-mpc.com/>

Email: info@Radiant-MPC.com

Website: radiant-mpc.com

Evaluation / decision-support only. Every Radiant tool is an aid to a Qualified Medical Physicist. All outputs must be independently reviewed before any clinical use. Do not transmit PHI through evaluation builds.