
1.장치관리자 -> USB Serial Port 확인

- 2. Modbus Rtu setting
- ① Serial port: COM7
- ② Baud: 9600
- 3 Data bits: 8
- 4 Stop bis: 1
- ⑤ Parity: none
- ⑥ Slave ID: 54
- 7 StartAddr: 0
- ® NumColis: 16
- 9 FunctionCode
- : Read Hoding Register (0x03)
- ① CSV: csv 저장위치
- 3. Connect click
- 4. Start click



NO	SENSOR	START	END	UNIT	FORMAT
1	NH₃	1	2	ppm	IEEE754 FLOAT
2	H ₂ S	3	4	ppm	IEEE754 FLOAT
3	PM2.5	5	6	μg/m³	IEEE754 FLOAT
4	PM10	7	8	μg/m³	IEEE754 FLOAT
5	PM1.0	9	10	µg/m³	IEEE754 FLOAT
6	Temp	11	12	°C , °F	IEEE754 FLOAT
7	Humi	12	14	%	IEEE754 FLOAT
8	TVOC	15	16	μg/m³	IEEE754 FLOAT

