


Production-Safety Tradeoff: VFA Penalty Sensitivity

Plan A: Linear coefficient sweep
(no constant penalty)



Plan B: Constant penalty sweep
(fixed linear $w=10$)

