

TOP DOWNTIME CONTRIBUTOR [Breakdown, Minor and Major Breakdown] 1. Filler Track 3 US Generator Speed Loss [1x/ 2.97 Hrs. OR 178 Mins.]

TOP DOWNTIME CONTRIBUTOR [Short Stop and Process Failure]

1. Tray_Packer Jammed Packs [13x/ 1.40 Hrs. OR 84 Mins.]

2. Straw_Applicator Missing/Fallen Straws [6x/ 0.67 Hrs. OR 40 Mins.]

3. Filler Loop no longer intact [2x/ 0.50 Hrs. OR 30 Mins.]

4. Filler Top Flap Dented [1x/ 0.42 Hrs. OR 25 Mins.]

5. Pasteurizer No Product [3x/ 0.33 Hrs. OR 20 Mins.]

6. Filler Outfeed Jammed Packs [2x/ 0.25 Hrs. OR 15 Mins.]

7. Filler Electrical Cabinet High Temperature [1x/ 0.18 Hrs. OR 11 Mins.]

8. Buffer_Table Jammed Packs [1x/ 0.17 Hrs. OR 10 Mins.]



