Tukang Copilot: Repair Report

#510de825b48c Demo mode: sample answers

Safety: CAUTION

Fuel nearby and the engine gets hot; work cold, away from flames.

Item

Honda Beat, spark plug area


Problem

Starter turns but the engine won't fire: likely no spark.

Cause fixed

Loose spark plug cap

Photo with the parts marked (SAM 3.1)



Before you start, make sure

[ ] The engine is off and has cooled (15 min)
[ ] No flames or cigarettes nearby

Steps (0/4 verified by camera)

[ ] 1. Switch the ignition off and let the engine cool for 10 minutes.
-> The key is in the OFF position.

[ ] 2. Open the side cover and find the plug cap (part number 1).
-> The plug cap is clearly visible.

[ ] 3. Push the plug cap straight in until it clicks.
-> The cap is fully seated, no gap.

[ ] 4. Refit the cover and press the starter while holding the brake.
-> The engine runs.

The engine starts and idles steadily.

Tools

- 16 mm spark plug socket Rp25.000
- Fine sandpaper / wire brush Rp5.000

Parts

- NGK CPR8EA-9 plug (spare) Rp25.000

Estimated parts cost: Rp25.000 ~20 min

Typical shop price (labour + parts): Rp60.000
Saved by doing it yourself (parts only): Rp35.000

What the AI did

- 0s Scanned your words for hazards (gas, mains, brakes...): clear [code]
- 1s Looked at the photo: Honda Beat, spark plug area, 3 parts located [muse-spark-1.3]
- 1s Outlined 3 of 3 parts on your photo (pixel masks) [sam-3.1] 0.2s
- 2s Most likely: Loose spark plug cap (55%), out of 3 causes [muse-spark-1.3]
- 3s Only 55% sure (below 60%): asked one question instead of guessing
- 3s Got your answer, re-ran the diagnosis
- 4s Most likely: Loose spark plug cap (55%), out of 3 causes [muse-spark-1.3]
- 4s Planned 4 steps for: Loose spark plug cap [muse-spark-1.3]
- 5s Plan checked by safety rules in code: passed (CAUTION) [code]

Under the hood: models used

- Text safety gate: rules in code
- Look at photo: muse-spark-1.3
- Mark parts: sam-3.1 0.2s
- Diagnose: muse-spark-1.3
- Plan steps: muse-spark-1.3
- Plan safety gate: rules in code

Light repairs only. Prices are estimates. For gas, house wiring, or high voltage, call a professional.

Mechanic brief

Print this page or show it to the workshop so they don't start from zero.

Status

Owner asked for a mechanic

What was found

Honda Beat, spark plug area

Starter turns but the engine won't fire: likely no spark.

Seen in the photo: Plug cap not fully seated

- Loose spark plug cap (55%): Cap looks unseated in the photo
- Fouled spark plug (35%): Hard start in the morning
- Clogged air filter (10%)

Parts marked: 1. Spark plug cap, 2. Ignition cable, 3. Air filter box

What was tried

- Loose spark plug cap

Owner's photos




Photo 1