Tukang Copilot

Repair Report

#629b51ac611e · Demo mode: sample answers

CAUTION Safety

Fuel nearby and the engine gets hot; work cold, away from flames.

Item

Honda Beat, spark plug area

Problem

Starter turns but the engine won't fire: likely no spark.

Cause worked on

Loose spark plug cap

Photo with the parts marked (SAM 3.1)



Likely causes

70%	Loose spark plug cap
22%	Fouled spark plug
8%	Clogged air filter

Before you start, make sure

- [ ] The engine is off and has cooled (15 min)
- [ ] No flames or cigarettes nearby

Steps (0/4 verified by camera)

1. Switch the ignition off and let the engine cool for 10 minutes.
   -> The key is in the OFF position.
2. Open the side cover and find the plug cap (part number 1).
   -> The plug cap is clearly visible.
3. Push the plug cap straight in until it clicks.
   -> The cap is fully seated, no gap.
4. Refit the cover and press the starter while holding the brake.
   -> The engine runs.

The engine starts and idles steadily.

Tools

- 16 mm spark plug socket	**Rp25.000**
- Fine sandpaper / wire brush	**Rp5.000**

Parts

- NGK CPR8EA-9 plug (spare)	**Rp25.000**

Estimated parts cost: Rp25.000 ~20 min

Typical shop price (labour + parts): Rp60.000
Saved by doing it yourself (parts only): Rp35.000

What the AI did

- 0s Scanned your words for hazards (gas, mains, brakes...): clear [code]
- 1s Looked at the photo: Honda Beat, spark plug area, 3 parts located [muse-spark-1.3]
- 2s Outlined 3 of 3 parts on your photo (pixel masks) [sam-3.1] 0.4s
- 2s Most likely: Loose spark plug cap (55%), out of 3 causes [muse-spark-1.3]
- 3s Only 55% sure (below 60%): asked one question instead of guessing
- 3s Got your answer, re-ran the diagnosis
- 4s Most likely: Loose spark plug cap (70%), out of 3 causes [muse-spark-1.3]
- 4s Planned 4 steps for: Loose spark plug cap [muse-spark-1.3]
- 5s Plan checked by safety rules in code: passed (CAUTION) [code]

Under the hood: models used

- Text safety gate: rules in code
- Look at photo: muse-spark-1.3
- Mark parts: sam-3.1 0.4s
- Diagnose: muse-spark-1.3
- Plan steps: muse-spark-1.3
- Plan safety gate: rules in code

Light repairs only. Prices are estimates. For gas, house wiring, or high voltage, call a professional.

Tukang Copilot
Mechanic brief

Print this page or show it to the workshop so they don't start from zero.

Status

Owner asked for a mechanic

What was found

Honda Beat, spark plug area
Starter turns but the engine won't fire: likely no spark.
Seen in the photo: Plug cap not fully seated
- Loose spark plug cap (70%): Fuel smell when cranking: fuel arrives, the spark is missing; Cap looks unseated in the photo
- Fouled spark plug (22%): Hard start in the morning
- Clogged air filter (8%)
Parts marked: 1. Spark plug cap, 2. Ignition cable, 3. Air filter box

What was tried

- Loose spark plug cap

Owner's photos



Photo 1