

DATA REMOTE

Nama Pelanggan	: BANK SYARIAH INDONESIA TBK.	Nomor Jaringan	: 2024428443
Contact Person	: -	Nomor Telepon	: -
Alamat	: JL sultan hasanudin tambun selatan kabupaten bekasi		
Kota	:	Propinsi	:
No. SPK	: 306054/WO-LA/2025	Tanggal	: 06-Aug-2025 07:10
Jam Perintah	: 06-Aug-2025 07:10	Jam Persiapan	: 06-Aug-2025 08:33
Jam Berangkat	: 06-Aug-2025 08:50	Jam Tiba Di Lokasi	: 06-Aug-2025 09:51
Jam Mulai Kerja	: 06-Aug-2025 09:56	Jam Selesai Kerja	: 06-Aug-2025 11:09
Jam Pulang	:	Jam Tiba Di Kantor	:

GLOBAL CHECKLIST

DATA LOKASI	ELECTRICAL	ENVIRONMENT
Latitude 6°1549292	1. Output Tegangan yg mengacu ke modem	1. AC Pendingin Ruangan Ada
Longitude 107°356269	PLN UPS IT	2. Suhu Ruangan Perangkat 25°
Posisi Modem di Lt. dilantai	P-N 231.3 VAC 231.3 VAC 231.3 VAC	
Ruang atm centre	P-G 231.6 VAC 231.6 VAC 231.6 VAC	
	N-G 0.476 VAC 0.476 VAC 0.476 VAC	
	2. Grounding Bar terkoneksi ke	

INDOOR AREA CHECKLIST

PERANGKAT MODEM	QUALITY PARAMETER	STANDARD	QUALITY PARAMETER			
			NMS / ENGINEER	ON SITE / TEKNISI	PERBAIKAN	HASIL AKHIR
Indikator Modem	POWER	ON (Green)				
	109/DCD/LINK-WAN	ON				
Merek :	TD/TXD/103	Blink				
	RD/RXD/104	Blink				
	RTS/105	ON				
	CTS/106	ON				
	Alarm LED	ON				
	Front Panel Display : All STU Modem	Quality A No Counter CRC Error				
	Tainet Scorpio	Connected xxx KBps		Connected KBps		
Modem FO	Optical LED Alarm	Green (ON)				
LC Signal Quality (Checked by Kop)	STU 160	Jangkrik Keras				
	STU 1088/2304	SOS Keras				
	ADSL Modem	Bersih, No Noise				
LC Signal Quality (Checked by AVO Meter)	STU 1088/2304,	400–700 Ω (Tlkm Area)	Ω			
	Tainet	50–200 Ω (HRB Area)	Ω			
	Adtran Express	48-50 VDc (QUAD CES SHDSL)				

LINE CHECKLIST

CHECK POINT	LINE CHECKLIST	STANDARD	EXISTING	PERBAIKAN	HASIL AKHIR
Site Area	Kabel RJ-11	No Berkarat, No Bad Contact/Putus			
	Phone Box	No Berkarat, No Bad Contact/Putus			
	KTB/DP Wall	No Berkarat, No Bad Contact/Putus			
	DP Telkom	No Berkarat, No Bad Contact/Putus			
	Sub Gedung	No Berkarat, No Bad Contact/Putus			
	MDF Gedung	No Berkarat, No Bad Contact/Putus			
	T-Line Gedung	No Grounded, No Noised,Tdk Putus Sedikit Terminasi No Paralel Line Detected Tahanan Loop : 200-400 Ω	Ω		
HRB/R.Lintas	T-Line (TX,LC)	No Grounded, No Noised,Tdk Putus Tahanan Loop : 010-100 Ω	Ω		
	Kabel Data	OK, Tidak Kendor, Tdk Putus			
	Port Sentral	OK, Tidak Kendor, Tdk Putus			
Line FO	Cek Signal FO	OK, Signal Balik, Tidak Putus			
	Koneksi OTB	OK, Tidak Kendor, Tdk Putus			
Tes Konektivitas	Bit Error Rate	Durasi 15 Menit, no error			
	Ping	100 % reply, < 50 ms			

DATA PERANGKAT

EXISTING			TIDAK TERPAKAI		
Nama Barang	No. Reg	S/N	Nama Barang	No. Reg	S/N
BIVOCOM INDUSTRIAL 4G ROUTER 5 PORTS, DUAL SIM, WIFI, DUAL MODUL	B2WS0200137MA0606				
CABUT			PENGANTI / PASANG BARU		
Nama Barang	No. Reg	S/N	Nama Barang	No. Reg	S/N
ADAPTER 12V, 1.5A FOR BIVOCOM	B2WS0200138MA0514 B		ADAPTER 12V, 1.5A FOR BIVOCOM	B2WS0200138MA557B	

Note : pergantian psu

VERIFIKASI DAN PERSETUJUAN

	PELAKSANA	PELANGGAN	VERIFIKATOR
Nama	Abdul Gunawan ALMAJARA	sulle	
Tanggal	06-Aug-2025 11:09	06-Aug-2025 11:09	
Tanda Tangan	 TKT001/24793977	 306054/WG-LA/2025	