

Vehicle diagnostic report



Shop Name: The Complete Car Care Center
 Address: Ajit Arcade Kailash Colony
 Phone:
 Email: babbarrahul365@gmail.com

License #: DL 6CM 1070

VIN: WDD2120482A381047

Year:

Make: Mercedes

Model: 212.048 - E 200 CGI

Odometer: 77038 miles

Vehicle Software Version: V49.42

Diagnostic Application Version: 1.00.043

Test Time: 2021-07-26 17:19:24

Diagnostic path: Automatically Search

Inspection Result

Diagnostic Result

Fault	(15)	
ECM - Engine Control Module(ME)	(3)	Abnormal
	P034062 The Position Sensor For The Intake Camshaft (Cylinder Bank 1) Has An Electrical Fault.The Signal Comparison Is Faulty.	CURRENT And STORED
	P008A23 The Pressure In The Fuel Low Pressure Circuit Is Too Low.No Signal Change: Voltage Level Is Too Low.	CURRENT And STORED
	P061A98 The Torque Control Of The Control Unit Has A Malfunction.The Component Or The System Has Overtemperature.	CURRENT And STORED
ESM[EWM] - Electronic Selector module(N15/5)	(1)	Abnormal
	U042700 Implausible Data Were Received From The Electronic Ignition Lock.	STORED
ESP(R) - Electronic Stability program(N30/4)	(1)	Abnormal
	631d00 There Is A Fault In Control Unit "EZS".	STORED
MFK - Multifunction camera(A40/11)	(1)	Abnormal
	c14687 Communication With The Central Gateway Has A Malfunction.	CURRENT And STORED
PTS - PARKTRONIC(N62)	(7)	Abnormal
	c42700 Implausible Data Were Received From The Electronic Ignition Lock._	STORED
	925823 The Center Right Front Distance Sensor Has A Malfunction.No Signal Change: Voltage Level Is Too Low.	CURRENT And STORED
	924923 The Center Left Front Distance Sensor Has A Malfunction.No Signal Change: Voltage Level Is Too Low.	CURRENT And STORED
	925d23 The Outer Right Front Distance Sensor Has A Malfunction.No Signal Change: Voltage Level Is Too Low.	CURRENT And STORED
	925323 The Inner Right Front Distance Sensor Has A Malfunction.No Signal Change: Voltage Level Is Too Low.	CURRENT And STORED
	924e23 The Inner Left Front Distance Sensor Has A Malfunction.No Signal Change: Voltage Level Is Too Low.	CURRENT And STORED

OCP - Overhead Control panel(N70)	924423 The Outer Left Front Distance Sensor Has A Malfunction.No Signal Change: Voltage Level Is Too Low. (1)	CURRENT And STORED Abnormal
EZS - Electronic Ignition lock(N73)	974915 The Rear Interior Illumination Has A Malfunction. There Is A Short Circuit To Positive Or An Open Circuit. (2)	Current and stored Abnormal
RevETR_LF - Left Front Reversible Emergency Tensioning retractor(A76)	a25407 The Electric Steering Lock Has A Malfunction.There Is A Mechanical Fault.	STORED
	a25464 The Electric Steering Lock Has A Malfunction.There Is An Implausible Signal.	STORED
RevETR_LF - Left Front Reversible Emergency Tensioning retractor(A76)	(1)	Abnormal
Driver-side SAM - Front Signal Acquisition And Actuation module(N10/1)	520108 The CAN Message From Control Unit "N73 (Electronic Ignition Lock Control Unit)" Is Faulty.	STORED
	(2)	Abnormal
Rear SAM - Rear Signal Acquisition And Actuation module(N10/2)	B162A15 The Left Low Beam Has A Malfunction.There Is A Short Circuit To Positive Or An Open Circuit.	CURRENT And STORED
	B163A15 The Output For The Left Front Turn Signal Lamp Has A Malfunction.There Is A Short Circuit To Positive Or An Open Circuit.	CURRENT And STORED
Rear SAM - Rear Signal Acquisition And Actuation module(N10/2)	(3)	Abnormal
SRS - Supplemental Restraint system(N2/10)	B21F286 The Status " Circuit 15" Is Implausible.There Is An Incorrect Signal.	STORED
	B16EB15 The Output For The Right License Plate Lamp Has A Malfunction.There Is A Short Circuit To Positive Or An Open Circuit.	CURRENT And STORED
	U016800 Communication With The Electronic Ignition Lock Has A Malfunction._	STORED
SRS - Supplemental Restraint system(N2/10)	(3)	Abnormal
Audio/COMAND - Audio Or COMAND(A2-A2/56-A40/3)	9ce2 The Signal Line Of The Sensor For The Left Engine Hood Catch Has An Open Circuit.	CURRENT And STORED
	9c1a NECK-PRO Head Restraint " Front Passenger" Has An Open Circuit.	STORED
	9c14 NECK-PRO Head Restraint " Driver" Has An Open Circuit.	STORED
Audio/COMAND - Audio Or COMAND(A2-A2/56-A40/3)	(1)	Abnormal
IC - Instrument cluster(A1)	d017 MOST Communication Has A Malfunction (MOST Master Reporting Ring Break).	CURRENT And STORED
	(1)	Abnormal
DCU_LF - Left Front door(N69/1)	U118B00 Communication With Control Unit " Right Headlamp Range Adjustment" Has A Malfunction._	CURRENT And STORED
	(2)	Abnormal

	973d15 The Output For The Turn Signal Lamp In The Outside Mirror Has A Malfunction.There Is A Short Circuit To Positive Or An Open Circuit.	CURRENT And STORED
	9dd015 The Output For The Mirror Heater Has A Malfunction.There Is A Short Circuit To Positive Or An Open Circuit.	CURRENT And STORED
AC - Air Conditioning(N22/7)	(2)	Abnormal
	91bc87 The Actuator Motor For The Air Flap " Right B-pillar" Has A Malfunction.The Message Is Missing.	CURRENT And STORED
	91b887 The Actuator Motor For The Air Flap " Left B-pillar" Has A Malfunction.The Message Is Missing.	CURRENT And STORED
Normal	(12)	
FSCU - Control Unit'Fuel pump'(N118)		Normal
TCM - Transmission Control Module		Normal
SCCM - Steering Column module(N80)		Normal
RevETR_RF - Right Front Reversible Emergency Tensioning retractor(A76/1)		Normal
CGW[ZGW] - Central gateway(CGW[ZGW])		Normal
COU[ZBE] - Audio/COMAND Operating Unit		Normal
ZAN - Audio/COMAND display(A40/8)		Normal
ESA'Front Passenger' - Electric Seat Adjustment 'Front passenger'(N32/2)		Normal
ESA 'Driver' - Electric Seat Adjustment 'Drive'(N32/1)		Normal
DCU_RF - Right Front door(N69/2)		Normal
DCU_LR - Left Rear door(N69/3)		Normal
DCU_RR - Right Rear door(N69/4)		Normal