Nutan ITI, Chinawal APPENDIX "A"

APPENDIX "A" CRAFTSMEN TRAINING SCHEME PROGRESS CARD

Trainee Name: Paresh Chaudhari

Roll No : 2 Unit: Unit 1 - First Year

Batch : 2019-2021 Trade : Fitter
Addmission Date : Date Of Leaving:

Auu	mission date :	Date Of Leaving	J.		
Sr No	Exercises Done During the Week	Within Date	Grades	I. Initial	G. I Initials
1					
2					
3					
4					
5	Safe disposal of waste materials	14 Aug - 14 Aug			
6	Safe disposal of waste materials	14 Aug - 14 Aug			
7	Safe disposal of waste materials	14 Aug - 14 Aug			
8	Safe disposal of waste materials	14 Aug - 14 Aug			
9					
10	Safe disposal of waste materials	14 Aug - 14 Aug			
11					
12	Safe disposal of waste materials	14 Aug - 14 Aug			
13	Safe disposal of waste materials	14 Aug - 14 Aug			
14	Safe disposal of waste materials	14 Aug - 14 Aug			
15	Safe disposal of waste materials	14 Aug - 14 Aug			
16	Safe disposal of waste materials	14 Aug - 14 Aug			
17	Safe disposal of waste materials	14 Aug - 14 Aug			
18	Safe disposal of waste materials	14 Aug - 14 Aug			
19	Safe disposal of waste materials	14 Aug - 14 Aug			
20	Safe disposal of waste materials	14 Aug - 14 Aug			
21	Safe disposal of waste materials	14 Aug - 14 Aug			
22	Safe disposal of waste materials	14 Aug - 14 Aug			
23	Safe disposal of waste materials	14 Aug - 14 Aug			
24	Safe disposal of waste materials	14 Aug - 14 Aug			
25	Safe disposal of waste materials	14 Aug - 14 Aug			

	1	ı		
26	Hazard identification and avoldance	14 Aug - 14 Aug		
27	Hazard identification and avoldance	14 Aug - 14 Aug		
28	Identification the categories of the safety sing	14 Aug - 14 Aug		
29	Identification the categories of the safety sing	14 Aug - 14 Aug		
30	Identification the categories of the safety sing	14 Aug - 14 Aug		
31	Identification the categories of the safety sing	14 Aug - 14 Aug		
32	Preventive measures for electrical accidents	16 Aug - 16 Aug		
33	Preventive measures for electrical accidents	16 Aug - 16 Aug		
34	Practice on fire extinguisher	16 Aug - 16 Aug		
35	Practice on fire extinguisher	16 Aug - 16 Aug		
36	Precautions while working in fitting jobs	16 Aug - 16 Aug		
37	Precautions while working in fitting jobs	16 Aug - 16 Aug		
38	Fitter tools and equipment	16 Aug - 16 Aug		
39	Fitter tools and equipment	16 Aug - 16 Aug		
40	Identification of marking and sawing tools	19 Aug - 19 Aug		
41	Identification of marking and sawing tools	19 Aug - 19 Aug		
42	Visual inspection of raw materials	21 Aug - 21 Aug		
43	Visual inspection of raw materials	21 Aug - 21 Aug		
44				
45				
46				
47				
48				
49				
50				
51				
52				
53				
54				
55				
56				
57				

58			
59			
60			
61			
62			
63			
64			
65			
66			
67			
68			
69			
70			
71			
72			
73			
74			
75			
76			
77			
78			
79			
80			
81			
82			
83			
84			
85			
86			
87			
88			
89			

90				
91				
92				
93				
94				
95				
96				
97				
98				
99				
100				
101				
102				
103				
104				
105				
106				
107				
108				
109				
110				
111				
112	a d sa	19 Jul - 05 Jul		
113				
114				
115				
116				
117				
118				
119				
120				
121				

122			
123			
124			
125			
126			
127			
128			
129			
130			
131			
132			
133			
134			
135			
136			
137			
138			
139			
140			
141			
142			
143			
144			
		A = 799 8 = 707	% Above Го 79%

C = 60 To 69% D = 59% Below