

EdgeAI Predictive Monitor -- Motor-Driver Rig Wiring

Arduino Uno + CNC Shield V3, one driver socket per motor axis. Shared ~ENABLE line on D8, active-LOW. Uno pins named by header number.

Report ref: Chapter 5 / Appendix B.3. Set each driver's current-limit trimpot before running: A4988 Vref = I_{max} x 8 x R_{sense}, DRV8825 Vref = I_{max} / 2.

