

# FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility  
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

## INCIDENT REPORT

### Incident Report: Security (Unauthorized Access)

Tailgating

**Equipment ID: CH104**

|                                                  |
|--------------------------------------------------|
| Document Number: INC-133                         |
| Revision: Final                                  |
| Classification: CONFIDENTIAL - INTERNAL USE ONLY |
| Prepared by: Engineering / QA Department         |
| Approved by: Plant Manager                       |

## 1. Incident Overview

### 1.1 Basic Information

| Parameter             | Value                              |
|-----------------------|------------------------------------|
| Incident ID           | INC-133                            |
| Type                  | Security (Unauthorized Access)     |
| Date & Time           | 2023-02-21 20:00                   |
| Location / Department | Utilities                          |
| Associated Asset      | CH104                              |
| Asset Name            | CH104 Chiller                      |
| Reported By           | Employee 14 (Engineer)             |
| Investigator          | Farah Shaikh (Food Safety Officer) |

## 2. Description of Event

On 2023-02-21 at 20:00, an incident classified as 'Security (Unauthorized Access)' occurred. The primary observation was: Employee tailgated through secure door.. The area was secured by the shift supervisor immediately after the event.

The incident occurred during operation/maintenance of equipment CH104 (CH104 Chiller). Refer to equipment manual MAN-CH104-001 for technical context.

## 3. Immediate Actions Taken

- Secured the area and stopped relevant machinery (if applicable).
- Administered first aid / contained spill / quarantined product (as per incident type).
- Notified the Plant Manager and EHS/QC department.
- Initial mitigation applied: Remind staff to use individual badges.

## 4. Root Cause Analysis (Summary)

A formal investigation was conducted. The preliminary root causes identified include inadequate risk perception, equipment failure, or procedural deviation. (A full RCA report is generated separately for critical incidents).

## 5. Corrective and Preventive Actions (CAPA)

| Action Description                     | Owner            | Target Date | Status      |
|----------------------------------------|------------------|-------------|-------------|
| Remind staff to use individual badges. | Farah Shaikh     | 2023-02-28  | Closed      |
| Review and update relevant SOP/RA      | Employee 14      | 2023-03-07  | In Progress |
| Conduct toolbox talk with shift team   | Shift Supervisor | 2023-02-23  | Closed      |

## 6. Signatures & Closure

---

Report Prepared By: Employee 14  
Date: 2023-02-22

Approved By: Farah Shaikh  
Date: 2023-02-23