

FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

RCA REPORT

Root Cause Analysis (RCA)

Subject: Pump cavitation in water transfer line

Equipment ID: WT104

Document Number: RCA-011
Revision: Final
Classification: CONFIDENTIAL - INTERNAL USE ONLY
Prepared by: Engineering / QA Department
Approved by: Plant Manager

1. RCA Information

1.1 Overview

Parameter	Value
RCA ID	RCA-011
Date of RCA	2023-03-30
Reference Event/Incident ID	FE-011
Equipment / Asset	WT104 - WT104 Water Treatment Unit
Department	Water Treatment
Facilitator	Employee 12 (Engineer)
Methodology Used	5-Whys

2. Problem Statement

The following issue occurred leading to a disruption in operations, quality, or safety: Pump cavitation in water transfer line. The immediate impact required corrective action to stabilize the process.

3. 5-Whys Analysis

The cross-functional team conducted a 5-Whys analysis to drill down to the systemic root cause.

Question	Answer
Why did the problem happen?	Pump cavitation in water transfer line
Why?	Because of component/process failure.
Why did it fail?	Because it reached its operational limit / was out of s
Why was it out of spec?	Because: Blocked water filter reduced suction pressure
Why? (Root Cause)	Systemic gap in maintenance plan or operational procedu

4. Identified Root Cause

Blocked water filter reduced suction pressure

This has been classified as a systemic failure requiring permanent corrective action.

5. Corrective and Preventive Actions (CAPA)

Action Items	Owner	Target Date
Flush water line, replace filter cartridge, verify suct	Employee 12	2023-04-06
Update Equipment Manual and PM Schedule	Arjun Nair	2023-04-13
Train operators on new procedure	Employee 7	2023-04-20

6. Sign-off

Plant Manager Approval: _____

Date: 2023-04-01