

# FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility  
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

## INSPECTION REPORT

### Inspection Report: Hygiene & Sanitation Inspection

Department: Bottle Washing

|                                                  |
|--------------------------------------------------|
| Document Number: INSP-025                        |
| Revision: Final                                  |
| Classification: CONFIDENTIAL - INTERNAL USE ONLY |
| Prepared by: Engineering / QA Department         |
| Approved by: Plant Manager                       |

## 1. Inspection Details

### 1.1 Overview

| Parameter              | Value                           |
|------------------------|---------------------------------|
| Inspection ID          | INSP-025                        |
| Type                   | Hygiene & Sanitation Inspection |
| Date & Time            | 2023-05-13 06:22                |
| Location / Department  | Bottle Washing                  |
| Inspector              | Anita Desai (QC Manager)        |
| Overall Score / Result | 93%                             |

## 2. Scope & Methodology

This report covers the Hygiene & Sanitation Inspection conducted in the Bottle Washing department. The inspection utilized standard FreshFlow checklists and visual observations. The objective is to ensure compliance with FSSAI, ISO 22000, and internal corporate standards.

## 3. Detailed Observations

| Area/Equipment | Observation                      | Status | Priority |
|----------------|----------------------------------|--------|----------|
| BW101          | Residue found on external cover. | Failed | High     |
| General Area   | Water pooled under machine.      | Failed | High     |
| BW101          | Residue found on external cover. | Failed | Medium   |
| General Area   | Water pooled under machine.      | Failed | High     |

## 4. Recommendations & Corrective Actions

All 'Failed' or 'Requires Attention' items must be entered into the CMMS or CAPA system within 24 hours of this report. Shift Supervisors are responsible for immediate mitigations.

## 5. Signatures

Inspected By: Anita Desai  
Date: 2023-05-13