

FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

INSPECTION REPORT

Inspection Report: Energy Leakage (Air/Steam) Survey

Department: Capping

Document Number: INSP-010
Revision: Final
Classification: CONFIDENTIAL - INTERNAL USE ONLY
Prepared by: Engineering / QA Department
Approved by: Plant Manager

1. Inspection Details

1.1 Overview

Parameter	Value
Inspection ID	INSP-010
Type	Energy Leakage (Air/Steam) Survey
Date & Time	2023-08-30 18:19
Location / Department	Capping
Inspector	Farah Shaikh (Food Safety Officer)
Overall Score / Result	Pass (with observations)

2. Scope & Methodology

This report covers the Energy Leakage (Air/Steam) Survey conducted in the Capping department. The inspection utilized standard FreshFlow checklists and visual observations. The objective is to ensure compliance with FSSAI, ISO 22000, and internal corporate standards.

3. Detailed Observations

Area/Equipment	Observation	Status	Priority
CM104	Audible air leak at fitting.	Failed	High
General Area	Audible air leak at fitting.	Failed	Medium
CM102	Insulation missing on pipe.	Failed	Medium
General Area	No leaks detected.	Failed	High
General Area	No leaks detected.	Failed	High
CM104	Audible air leak at fitting.	Failed	Medium
CM102	No leaks detected.	Failed	Medium

4. Recommendations & Corrective Actions

All 'Failed' or 'Requires Attention' items must be entered into the CMMS or CAPA system within 24 hours of this report. Shift Supervisors are responsible for immediate mitigations.

5. Signatures

Inspected By: Farah Shaikh
Date: 2023-08-30