

# FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility  
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

## INSPECTION REPORT

### Inspection Report: Safety Walkaround

Department: Mixing

|                                                  |
|--------------------------------------------------|
| Document Number: INSP-124                        |
| Revision: Final                                  |
| Classification: CONFIDENTIAL - INTERNAL USE ONLY |
| Prepared by: Engineering / QA Department         |
| Approved by: Plant Manager                       |

## 1. Inspection Details

### 1.1 Overview

| Parameter              | Value                              |
|------------------------|------------------------------------|
| Inspection ID          | INSP-124                           |
| Type                   | Safety Walkaround                  |
| Date & Time            | 2023-07-14 09:13                   |
| Location / Department  | Mixing                             |
| Inspector              | Farah Shaikh (Food Safety Officer) |
| Overall Score / Result | Pass (with observations)           |

## 2. Scope & Methodology

This report covers the Safety Walkaround conducted in the Mixing department. The inspection utilized standard FreshFlow checklists and visual observations. The objective is to ensure compliance with FSSAI, ISO 22000, and internal corporate standards.

## 3. Detailed Observations

| Area/Equipment | Observation                  | Status | Priority |
|----------------|------------------------------|--------|----------|
| M105           | Guard securely bolted.       | Passed | Low      |
| M104           | Trip hazard (cable) present. | Failed | High     |
| M101           | Guard securely bolted.       | Passed | Low      |
| M105           | E-Stop button unobstructed.  | Passed | Low      |
| M101           | Guard securely bolted.       | Passed | Low      |

## 4. Recommendations & Corrective Actions

All 'Failed' or 'Requires Attention' items must be entered into the CMMS or CAPA system within 24 hours of this report. Shift Supervisors are responsible for immediate mitigations.

## 5. Signatures

Inspected By: Farah Shaikh  
Date: 2023-07-14