

# FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility  
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

## INCIDENT REPORT

### Incident Report: Security (Unauthorized Access)

Unescorted visitor

**Equipment ID: M105**

|                                                  |
|--------------------------------------------------|
| Document Number: INC-130                         |
| Revision: Final                                  |
| Classification: CONFIDENTIAL - INTERNAL USE ONLY |
| Prepared by: Engineering / QA Department         |
| Approved by: Plant Manager                       |

## 1. Incident Overview

### 1.1 Basic Information

| Parameter             | Value                          |
|-----------------------|--------------------------------|
| Incident ID           | INC-130                        |
| Type                  | Security (Unauthorized Access) |
| Date & Time           | 2023-06-03 13:30               |
| Location / Department | Mixing                         |
| Associated Asset      | M105                           |
| Asset Name            | M105 Mixing Tank               |
| Reported By           | Employee 9 (Operator)          |
| Investigator          | Anita Desai (QC Manager)       |

## 2. Description of Event

On 2023-06-03 at 13:30, an incident classified as 'Security (Unauthorized Access)' occurred. The primary observation was: Contractor found wandering in high-care filling area.. The area was secured by the shift supervisor immediately after the event.

The incident occurred during operation/maintenance of equipment M105 (M105 Mixing Tank). Refer to equipment manual MAN-M105-001 for technical context.

## 3. Immediate Actions Taken

- Secured the area and stopped relevant machinery (if applicable).
- Administered first aid / contained spill / quarantined product (as per incident type).
- Notified the Plant Manager and EHS/QC department.
- Initial mitigation applied: Escorted out. Toolbox talk on visitor policy.

## 4. Root Cause Analysis (Summary)

A formal investigation was conducted. The preliminary root causes identified include inadequate risk perception, equipment failure, or procedural deviation. (A full RCA report is generated separately for critical incidents).

## 5. Corrective and Preventive Actions (CAPA)

| Action Description                            | Owner            | Target Date | Status      |
|-----------------------------------------------|------------------|-------------|-------------|
| Escorted out. Toolbox talk on visitor policy. | Anita Desai      | 2023-06-10  | Closed      |
| Review and update relevant SOP/RA             | Employee 9       | 2023-06-17  | In Progress |
| Conduct toolbox talk with shift team          | Shift Supervisor | 2023-06-05  | Closed      |

## 6. Signatures & Closure

---

Report Prepared By: Employee 9  
Date: 2023-06-04

Approved By: Anita Desai  
Date: 2023-06-05