

# FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility  
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

## RCA REPORT

### Root Cause Analysis (RCA)

Subject: Unexpected failure of UPS101 Power Backup causing production delay.

**Equipment ID: UPS101**

|                                                  |
|--------------------------------------------------|
| Document Number: RCA-193                         |
| Revision: Final                                  |
| Classification: CONFIDENTIAL - INTERNAL USE ONLY |
| Prepared by: Engineering / QA Department         |
| Approved by: Plant Manager                       |

## 1. RCA Information

### 1.1 Overview

| Parameter                   | Value                        |
|-----------------------------|------------------------------|
| RCA ID                      | RCA-193                      |
| Date of RCA                 | 2023-03-21                   |
| Reference Event/Incident ID | INC-159                      |
| Equipment / Asset           | UPS101 - UPS101 Power Backup |
| Department                  | Utilities                    |
| Facilitator                 | Employee 14 (Engineer)       |
| Methodology Used            | 5-Whys                       |

## 2. Problem Statement

The following issue occurred leading to a disruption in operations, quality, or safety: Unexpected failure of UPS101 Power Backup causing production delay.. The immediate impact required corrective action to stabilize the process.

## 3. 5-Whys Analysis

The cross-functional team conducted a 5-Whys analysis to drill down to the systemic root cause.

| Question                    | Answer                                                  |
|-----------------------------|---------------------------------------------------------|
| Why did the problem happen? | Unexpected failure of UPS101 Power Backup causing produ |
| Why?                        | Because of component/process failure.                   |
| Why did it fail?            | Because it reached its operational limit / was out of s |
| Why was it out of spec?     | Because: Wear and tear combined with missed preventive  |
| Why? (Root Cause)           | Systemic gap in maintenance plan or operational procedu |

## 4. Identified Root Cause

Wear and tear combined with missed preventive maintenance schedule.  
This has been classified as a systemic failure requiring permanent corrective action.

## 5. Corrective and Preventive Actions (CAPA)

| Action Items                                            | Owner       | Target Date |
|---------------------------------------------------------|-------------|-------------|
| Replace worn parts. Implement automated PM alerts in CM | Employee 14 | 2023-03-28  |
| Update Equipment Manual and PM Schedule                 | Employee 14 | 2023-04-04  |
| Train operators on new procedure                        | Employee 2  | 2023-04-11  |

## 6. Sign-off

---

Plant Manager Approval: \_\_\_\_\_

Date: 2023-03-23