

# FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility  
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

## INSPECTION REPORT

### Inspection Report: 5S Audit

Department: Capping

|                                                  |
|--------------------------------------------------|
| Document Number: INSP-052                        |
| Revision: Final                                  |
| Classification: CONFIDENTIAL - INTERNAL USE ONLY |
| Prepared by: Engineering / QA Department         |
| Approved by: Plant Manager                       |

## 1. Inspection Details

### 1.1 Overview

| Parameter              | Value                           |
|------------------------|---------------------------------|
| Inspection ID          | INSP-052                        |
| Type                   | 5S Audit                        |
| Date & Time            | 2023-09-16 14:20                |
| Location / Department  | Capping                         |
| Inspector              | Rajesh Kulkarni (Plant Manager) |
| Overall Score / Result | 94%                             |

## 2. Scope & Methodology

This report covers the 5S Audit conducted in the Capping department. The inspection utilized standard FreshFlow checklists and visual observations. The objective is to ensure compliance with FSSAI, ISO 22000, and internal corporate standards.

## 3. Detailed Observations

| Area/Equipment | Observation             | Status | Priority |
|----------------|-------------------------|--------|----------|
| CM101          | Floor marking faded.    | Failed | High     |
| CM101          | Shadow board organized. | Passed | Low      |
| General Area   | Workstation clean.      | Passed | Low      |
| CM103          | Shadow board organized. | Passed | Low      |
| CM104          | Tools left on floor.    | Failed | Medium   |
| CM104          | Floor marking faded.    | Failed | Medium   |

## 4. Recommendations & Corrective Actions

All 'Failed' or 'Requires Attention' items must be entered into the CMMS or CAPA system within 24 hours of this report. Shift Supervisors are responsible for immediate mitigations.

## 5. Signatures

Inspected By: Rajesh Kulkarni  
Date: 2023-09-16