

# FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility  
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

## INCIDENT REPORT

### Incident Report: Safety (First Aid)

Minor cut

**Equipment ID: BW105**

|                                                  |
|--------------------------------------------------|
| Document Number: INC-040                         |
| Revision: Final                                  |
| Classification: CONFIDENTIAL - INTERNAL USE ONLY |
| Prepared by: Engineering / QA Department         |
| Approved by: Plant Manager                       |

## 1. Incident Overview

### 1.1 Basic Information

| Parameter             | Value                        |
|-----------------------|------------------------------|
| Incident ID           | INC-040                      |
| Type                  | Safety (First Aid)           |
| Date & Time           | 2023-11-20 16:48             |
| Location / Department | Bottle Washing               |
| Associated Asset      | BW105                        |
| Asset Name            | BW105 Bottle Washing Machine |
| Reported By           | Employee 17 (Operator)       |
| Investigator          | Anita Desai (QC Manager)     |

## 2. Description of Event

On 2023-11-20 at 16:48, an incident classified as 'Safety (First Aid)' occurred. The primary observation was: Operator cut finger on sharp edge of guide rail.. The area was secured by the shift supervisor immediately after the event.

The incident occurred during operation/maintenance of equipment BW105 (BW105 Bottle Washing Machine). Refer to equipment manual MAN-BW105-001 for technical context.

## 3. Immediate Actions Taken

- Secured the area and stopped relevant machinery (if applicable).
- Administered first aid / contained spill / quarantined product (as per incident type).
- Notified the Plant Manager and EHS/QC department.
- Initial mitigation applied: Cleaned and bandaged. Grind sharp edges on rails.

## 4. Root Cause Analysis (Summary)

A formal investigation was conducted. The preliminary root causes identified include inadequate risk perception, equipment failure, or procedural deviation. (A full RCA report is generated separately for critical incidents).

## 5. Corrective and Preventive Actions (CAPA)

| Action Description                                | Owner            | Target Date | Status      |
|---------------------------------------------------|------------------|-------------|-------------|
| Cleaned and bandaged. Grind sharp edges on rails. | Anita Desai      | 2023-11-27  | Closed      |
| Review and update relevant SOP/RA                 | Employee 17      | 2023-12-04  | In Progress |
| Conduct toolbox talk with shift team              | Shift Supervisor | 2023-11-22  | Closed      |

## 6. Signatures & Closure

Report Prepared By: Employee 17  
Date: 2023-11-21

Approved By: Anita Desai  
Date: 2023-11-22