

FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

RCA REPORT

Root Cause Analysis (RCA)

Subject: Air compressor pressure loss

Equipment ID: CV104

Document Number: RCA-020
Revision: Final
Classification: CONFIDENTIAL - INTERNAL USE ONLY
Prepared by: Engineering / QA Department
Approved by: Plant Manager

1. RCA Information

1.1 Overview

Parameter	Value
RCA ID	RCA-020
Date of RCA	2023-03-03
Reference Event/Incident ID	FE-020
Equipment / Asset	CV104 - CV104 Conveyor Belt
Department	Packaging
Facilitator	Employee 12 (Engineer)
Methodology Used	Fault Tree Analysis

2. Problem Statement

The following issue occurred leading to a disruption in operations, quality, or safety: Air compressor pressure loss. The immediate impact required corrective action to stabilize the process.

3. 5-Whys Analysis

The cross-functional team conducted a 5-Whys analysis to drill down to the systemic root cause.

Question	Answer
Why did the problem happen?	Air compressor pressure loss
Why?	Because of component/process failure.
Why did it fail?	Because it reached its operational limit / was out of s
Why was it out of spec?	Because: Air leakage from cracked pneumatic hose near f
Why? (Root Cause)	Systemic gap in maintenance plan or operational procedu

4. Identified Root Cause

Air leakage from cracked pneumatic hose near filling valve manifold

This has been classified as a systemic failure requiring permanent corrective action.

5. Corrective and Preventive Actions (CAPA)

Action Items	Owner	Target Date
Replace hose, replace air filter, perform plant air lea	Employee 12	2023-03-10
Update Equipment Manual and PM Schedule	Arjun Nair	2023-03-17
Train operators on new procedure	Farah Shaikh	2023-03-24

6. Sign-off

Plant Manager Approval: _____

Date: 2023-03-05