

# FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility  
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

## INCIDENT REPORT

### Incident Report: Quality (Product Contamination)

Foreign object (Metal)

**Equipment ID: FM102**

|                                                  |
|--------------------------------------------------|
| Document Number: INC-076                         |
| Revision: Final                                  |
| Classification: CONFIDENTIAL - INTERNAL USE ONLY |
| Prepared by: Engineering / QA Department         |
| Approved by: Plant Manager                       |

## 1. Incident Overview

### 1.1 Basic Information

| Parameter             | Value                              |
|-----------------------|------------------------------------|
| Incident ID           | INC-076                            |
| Type                  | Quality (Product Contamination)    |
| Date & Time           | 2023-11-24 09:08                   |
| Location / Department | Filling                            |
| Associated Asset      | FM102                              |
| Asset Name            | FM102 Bottle Filling Machine       |
| Reported By           | Employee 20 (Engineer)             |
| Investigator          | Farah Shaikh (Food Safety Officer) |

## 2. Description of Event

On 2023-11-24 at 09:08, an incident classified as 'Quality (Product Contamination)' occurred. The primary observation was: Metal shaving found in empty bottle after washing.. The area was secured by the shift supervisor immediately after the event.

The incident occurred during operation/maintenance of equipment FM102 (FM102 Bottle Filling Machine). Refer to equipment manual MAN-FM102-001 for technical context.

## 3. Immediate Actions Taken

- Secured the area and stopped relevant machinery (if applicable).
- Administered first aid / contained spill / quarantined product (as per incident type).
- Notified the Plant Manager and EHS/QC department.
- Initial mitigation applied: Quarantine batch. Inspect washer nozzles and chain for wear.

## 4. Root Cause Analysis (Summary)

A formal investigation was conducted. The preliminary root causes identified include inadequate risk perception, equipment failure, or procedural deviation. (A full RCA report is generated separately for critical incidents).

## 5. Corrective and Preventive Actions (CAPA)

| Action Description                                     | Owner            | Target Date | Status      |
|--------------------------------------------------------|------------------|-------------|-------------|
| Quarantine batch. Inspect washer nozzles and chain for | Farah Shaikh     | 2023-12-01  | Closed      |
| Review and update relevant SOP/RA                      | Employee 20      | 2023-12-08  | In Progress |
| Conduct toolbox talk with shift team                   | Shift Supervisor | 2023-11-26  | Closed      |

## 6. Signatures & Closure

---

Report Prepared By: Employee 20  
Date: 2023-11-25

Approved By: Farah Shaikh  
Date: 2023-11-26