

# FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility  
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

## INSPECTION REPORT

### Inspection Report: Energy Leakage (Air/Steam) Survey

Department: Packaging

|                                                  |
|--------------------------------------------------|
| Document Number: INSP-279                        |
| Revision: Final                                  |
| Classification: CONFIDENTIAL - INTERNAL USE ONLY |
| Prepared by: Engineering / QA Department         |
| Approved by: Plant Manager                       |

## 1. Inspection Details

### 1.1 Overview

| Parameter              | Value                              |
|------------------------|------------------------------------|
| Inspection ID          | INSP-279                           |
| Type                   | Energy Leakage (Air/Steam) Survey  |
| Date & Time            | 2023-12-16 11:59                   |
| Location / Department  | Packaging                          |
| Inspector              | Farah Shaikh (Food Safety Officer) |
| Overall Score / Result | Pass (with observations)           |

## 2. Scope & Methodology

This report covers the Energy Leakage (Air/Steam) Survey conducted in the Packaging department. The inspection utilized standard FreshFlow checklists and visual observations. The objective is to ensure compliance with FSSAI, ISO 22000, and internal corporate standards.

## 3. Detailed Observations

| Area/Equipment | Observation                  | Status | Priority |
|----------------|------------------------------|--------|----------|
| CV104          | Audible air leak at fitting. | Failed | High     |
| General Area   | Steam trap blowing through.  | Failed | High     |
| General Area   | Audible air leak at fitting. | Failed | Medium   |
| General Area   | No leaks detected.           | Failed | High     |

## 4. Recommendations & Corrective Actions

All 'Failed' or 'Requires Attention' items must be entered into the CMMS or CAPA system within 24 hours of this report. Shift Supervisors are responsible for immediate mitigations.

## 5. Signatures

Inspected By: Farah Shaikh  
Date: 2023-12-16