

FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

RCA REPORT

Root Cause Analysis (RCA)

Subject: Filling nozzle blockage causing low fill level

Equipment ID: CV103

Document Number: RCA-036
Revision: Final
Classification: CONFIDENTIAL - INTERNAL USE ONLY
Prepared by: Engineering / QA Department
Approved by: Plant Manager

1. RCA Information

1.1 Overview

Parameter	Value
RCA ID	RCA-036
Date of RCA	2023-12-07
Reference Event/Incident ID	FE-036
Equipment / Asset	CV103 - CV103 Conveyor Belt
Department	Packaging
Facilitator	Employee 10 (Engineer)
Methodology Used	5-Whys

2. Problem Statement

The following issue occurred leading to a disruption in operations, quality, or safety: Filling nozzle blockage causing low fill level. The immediate impact required corrective action to stabilize the process.

3. 5-Whys Analysis

The cross-functional team conducted a 5-Whys analysis to drill down to the systemic root cause.

Question	Answer
Why did the problem happen?	Filling nozzle blockage causing low fill level
Why?	Because of component/process failure.
Why did it fail?	Because it reached its operational limit / was out of s
Why was it out of spec?	Because: Nozzle clogged by syrup residue due to incompl
Why? (Root Cause)	Systemic gap in maintenance plan or operational procedu

4. Identified Root Cause

Nozzle clogged by syrup residue due to incomplete CIP

This has been classified as a systemic failure requiring permanent corrective action.

5. Corrective and Preventive Actions (CAPA)

Action Items	Owner	Target Date
Clean filling nozzle, verify CIP spray pattern, record	Employee 10	2023-12-14
Update Equipment Manual and PM Schedule	Anita Desai	2023-12-21
Train operators on new procedure	Employee 5	2023-12-28

6. Sign-off

Plant Manager Approval: _____

Date: 2023-12-09