

FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

RCA REPORT

Root Cause Analysis (RCA)

Subject: Unexpected failure of FM103 Bottle Filling Machine causing production delay.

Equipment ID: FM103

Document Number: RCA-119
Revision: Final
Classification: CONFIDENTIAL - INTERNAL USE ONLY
Prepared by: Engineering / QA Department
Approved by: Plant Manager

1. RCA Information

1.1 Overview

Parameter	Value
RCA ID	RCA-119
Date of RCA	2023-03-15
Reference Event/Incident ID	INC-208
Equipment / Asset	FM103 - FM103 Bottle Filling Machine
Department	Filling
Facilitator	Employee 16 (Engineer)
Methodology Used	Fishbone (Ishikawa)

2. Problem Statement

The following issue occurred leading to a disruption in operations, quality, or safety: Unexpected failure of FM103 Bottle Filling Machine causing production delay.. The immediate impact required corrective action to stabilize the process.

3. 5-Whys Analysis

The cross-functional team conducted a 5-Whys analysis to drill down to the systemic root cause.

Question	Answer
Why did the problem happen?	Unexpected failure of FM103 Bottle Filling Machine caus
Why?	Because of component/process failure.
Why did it fail?	Because it reached its operational limit / was out of s
Why was it out of spec?	Because: Wear and tear combined with missed preventive
Why? (Root Cause)	Systemic gap in maintenance plan or operational procedu

4. Identified Root Cause

Wear and tear combined with missed preventive maintenance schedule.
This has been classified as a systemic failure requiring permanent corrective action.

5. Corrective and Preventive Actions (CAPA)

Action Items	Owner	Target Date
Replace worn parts. Implement automated PM alerts in CM	Employee 16	2023-03-22
Update Equipment Manual and PM Schedule	Employee 12	2023-03-29
Train operators on new procedure	Employee 10	2023-04-05

6. Sign-off

Plant Manager Approval: _____

Date: 2023-03-17