

# FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility  
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

## INSPECTION REPORT

### Inspection Report: Safety Walkaround

Department: Filling

|                                                  |
|--------------------------------------------------|
| Document Number: INSP-137                        |
| Revision: Final                                  |
| Classification: CONFIDENTIAL - INTERNAL USE ONLY |
| Prepared by: Engineering / QA Department         |
| Approved by: Plant Manager                       |

## 1. Inspection Details

### 1.1 Overview

| Parameter              | Value                           |
|------------------------|---------------------------------|
| Inspection ID          | INSP-137                        |
| Type                   | Safety Walkaround               |
| Date & Time            | 2023-10-12 08:44                |
| Location / Department  | Filling                         |
| Inspector              | Rajesh Kulkarni (Plant Manager) |
| Overall Score / Result | Pass (with observations)        |

## 2. Scope & Methodology

This report covers the Safety Walkaround conducted in the Filling department. The inspection utilized standard FreshFlow checklists and visual observations. The objective is to ensure compliance with FSSAI, ISO 22000, and internal corporate standards.

## 3. Detailed Observations

| Area/Equipment | Observation                 | Status | Priority |
|----------------|-----------------------------|--------|----------|
| FM101          | Guard securely bolted.      | Passed | Low      |
| General Area   | Fire extinguisher blocked.  | Failed | Medium   |
| FM103          | Guard securely bolted.      | Passed | Low      |
| FM104          | E-Stop button unobstructed. | Passed | Low      |
| FM101          | E-Stop button unobstructed. | Passed | Low      |
| General Area   | Fire extinguisher blocked.  | Failed | Medium   |

## 4. Recommendations & Corrective Actions

All 'Failed' or 'Requires Attention' items must be entered into the CMMS or CAPA system within 24 hours of this report. Shift Supervisors are responsible for immediate mitigations.

## 5. Signatures

Inspected By: Rajesh Kulkarni  
Date: 2023-10-12