

FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

RCA REPORT

Root Cause Analysis (RCA)

Subject: Pump cavitation in water transfer line

Equipment ID: M105

Document Number: RCA-025
Revision: Final
Classification: CONFIDENTIAL - INTERNAL USE ONLY
Prepared by: Engineering / QA Department
Approved by: Plant Manager

1. RCA Information

1.1 Overview

Parameter	Value
RCA ID	RCA-025
Date of RCA	2023-04-29
Reference Event/Incident ID	FE-025
Equipment / Asset	M105 - M105 Mixing Tank
Department	Mixing
Facilitator	Arjun Nair (Maintenance Engineer)
Methodology Used	Fishbone (Ishikawa)

2. Problem Statement

The following issue occurred leading to a disruption in operations, quality, or safety: Pump cavitation in water transfer line. The immediate impact required corrective action to stabilize the process.

3. 5-Whys Analysis

The cross-functional team conducted a 5-Whys analysis to drill down to the systemic root cause.

Question	Answer
Why did the problem happen?	Pump cavitation in water transfer line
Why?	Because of component/process failure.
Why did it fail?	Because it reached its operational limit / was out of s
Why was it out of spec?	Because: Blocked water filter reduced suction pressure
Why? (Root Cause)	Systemic gap in maintenance plan or operational procedu

4. Identified Root Cause

Blocked water filter reduced suction pressure

This has been classified as a systemic failure requiring permanent corrective action.

5. Corrective and Preventive Actions (CAPA)

Action Items	Owner	Target Date
Flush water line, replace filter cartridge, verify suct	Arjun Nair	2023-05-06
Update Equipment Manual and PM Schedule	Employee 6	2023-05-13
Train operators on new procedure	Employee 15	2023-05-20

6. Sign-off

Plant Manager Approval: _____

Date: 2023-05-01