

FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

RCA REPORT

Root Cause Analysis (RCA)

Subject: Filling nozzle blockage causing low fill level

Equipment ID: WT101

Document Number: RCA-033
Revision: Final
Classification: CONFIDENTIAL - INTERNAL USE ONLY
Prepared by: Engineering / QA Department
Approved by: Plant Manager

1. RCA Information

1.1 Overview

Parameter	Value
RCA ID	RCA-033
Date of RCA	2023-04-09
Reference Event/Incident ID	FE-033
Equipment / Asset	WT101 - WT101 Water Treatment Unit
Department	Water Treatment
Facilitator	Rajesh Kulkarni (Plant Manager)
Methodology Used	Fishbone (Ishikawa)

2. Problem Statement

The following issue occurred leading to a disruption in operations, quality, or safety: Filling nozzle blockage causing low fill level. The immediate impact required corrective action to stabilize the process.

3. 5-Whys Analysis

The cross-functional team conducted a 5-Whys analysis to drill down to the systemic root cause.

Question	Answer
Why did the problem happen?	Filling nozzle blockage causing low fill level
Why?	Because of component/process failure.
Why did it fail?	Because it reached its operational limit / was out of s
Why was it out of spec?	Because: Nozzle clogged by syrup residue due to incompl
Why? (Root Cause)	Systemic gap in maintenance plan or operational procedu

4. Identified Root Cause

Nozzle clogged by syrup residue due to incomplete CIP
This has been classified as a systemic failure requiring permanent corrective action.

5. Corrective and Preventive Actions (CAPA)

Action Items	Owner	Target Date
Clean filling nozzle, verify CIP spray pattern, record	Rajesh Kulkarni	2023-04-16
Update Equipment Manual and PM Schedule	Employee 4	2023-04-23
Train operators on new procedure	Employee 15	2023-04-30

6. Sign-off

Plant Manager Approval: _____

Date: 2023-04-11