

# FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility  
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

## INCIDENT REPORT

### Incident Report: Safety (First Aid)

Minor thermal burn

**Equipment ID: TK102**

|                                                  |
|--------------------------------------------------|
| Document Number: INC-222                         |
| Revision: Final                                  |
| Classification: CONFIDENTIAL - INTERNAL USE ONLY |
| Prepared by: Engineering / QA Department         |
| Approved by: Plant Manager                       |

## 1. Incident Overview

### 1.1 Basic Information

| Parameter             | Value                    |
|-----------------------|--------------------------|
| Incident ID           | INC-222                  |
| Type                  | Safety (First Aid)       |
| Date & Time           | 2023-01-22 04:01         |
| Location / Department | Water Treatment          |
| Associated Asset      | TK102                    |
| Asset Name            | TK102 Water Storage Tank |
| Reported By           | Anita Desai (QC Manager) |
| Investigator          | Anita Desai (QC Manager) |

## 2. Description of Event

On 2023-01-22 at 04:01, an incident classified as 'Safety (First Aid)' occurred. The primary observation was: Technician touched hot steam pipe.. The area was secured by the shift supervisor immediately after the event.

The incident occurred during operation/maintenance of equipment TK102 (TK102 Water Storage Tank). Refer to equipment manual MAN-TK102-001 for technical context.

## 3. Immediate Actions Taken

- Secured the area and stopped relevant machinery (if applicable).
- Administered first aid / contained spill / quarantined product (as per incident type).
- Notified the Plant Manager and EHS/QC department.
- Initial mitigation applied: Apply burn cream. Re-insulate exposed steam pipe section.

## 4. Root Cause Analysis (Summary)

A formal investigation was conducted. The preliminary root causes identified include inadequate risk perception, equipment failure, or procedural deviation. (A full RCA report is generated separately for critical incidents).

## 5. Corrective and Preventive Actions (CAPA)

| Action Description                                      | Owner            | Target Date | Status      |
|---------------------------------------------------------|------------------|-------------|-------------|
| Apply burn cream. Re-insulate exposed steam pipe sectio | Anita Desai      | 2023-01-29  | Closed      |
| Review and update relevant SOP/RA                       | Anita Desai      | 2023-02-05  | In Progress |
| Conduct toolbox talk with shift team                    | Shift Supervisor | 2023-01-24  | Closed      |

## 6. Signatures & Closure

Report Prepared By: Anita Desai

Date: 2023-01-23

Approved By: Anita Desai

Date: 2023-01-24