

# FreshFlow Beverages Pvt. Ltd.

FreshFlow Bottling Plant - Pune Production Facility  
FSSAI: 10012022000345 | ISO 22000:2018 / ISO 14001:2015

## STANDARD OPERATING PROCEDURE

### Maintenance Procedure for Labeling Line 86

Department: Labeling

|                                                  |
|--------------------------------------------------|
| Document Number: SOP-086                         |
| Revision: Rev 4.0                                |
| Classification: CONFIDENTIAL - INTERNAL USE ONLY |
| Prepared by: Engineering / QA Department         |
| Approved by: Plant Manager                       |

## Document Control Information

| Parameter        | Value                                               |
|------------------|-----------------------------------------------------|
| SOP Number       | SOP-086                                             |
| Title            | Maintenance Procedure for Labeling Line 86          |
| Department       | Labeling                                            |
| Plant            | FreshFlow Bottling Plant - Pune Production Facility |
| Prepared By      | Arjun Nair                                          |
| Reviewed By      | Rajesh Kulkarni                                     |
| Approved By      | Rajesh Kulkarni - Plant Manager                     |
| Issue Date       | 2021-04-16                                          |
| Next Review Date | 2025-12-21                                          |
| Revision         | Rev 3.0                                             |

## 1. Purpose

Apply labels correctly and consistently so all bottles carry accurate product information complying with FSSAI labeling regulations and FreshFlow brand standards.

## 2. Scope

Labeling department operators, quality inspectors, and maintenance technicians.

## 3. Prerequisites and Requirements

### 3.1 Training Requirements

- Labeling machine operation training
- Vision system calibration training

### 3.2 Tools and Materials Required

- Calibrated instruments as listed in the plant calibration schedule.
- Appropriate PPE as specified in Section 4.
- Completed permit-to-work (if required for maintenance activities).
- Access to relevant equipment manual and P&ID drawings.
- CMMS access to create and close work orders.

## 4. Health, Safety and Environmental Requirements

### ! WARNING

This SOP must not be carried out without appropriate PPE and, where required, a valid Permit to Work (SOP-SAF-006). If in doubt about safety, STOP and consult the Safety Officer (EMP009 / EMP017).

#### 4.1 Identified Hazards

- Hot melt glue (140-160°C) - thermal burn risk if contacted
- Solvents in label adhesive - ventilation required
- Cutting tools for label splicing - laceration risk

#### 4.2 Emergency Response

In case of any emergency during this procedure: Press the nearest Emergency Stop, alert personnel in the vicinity, call the Safety Officer and Shift Supervisor. Refer to the Emergency Response Plan (SOP-SAF-004) and site evacuation procedure.

## 5. Detailed Procedure

#### 5.1 Pre-Task Verification

1. Confirm the relevant equipment is available and no conflicting activities are planned.
2. Check shift handover log for any outstanding issues with this equipment.
3. Verify all required materials, tools, and chemicals are available and correctly labelled.
4. Obtain all required permits (PTW, hot work, confined space as applicable).
5. Brief all involved personnel on this SOP before starting.

#### 5.2 Main Procedure

1. Perform pre-task briefing with all involved team members.
2. Verify relevant equipment status on SCADA - confirm normal operating condition.
3. Carry out the main task following the equipment manual and technical drawings.
4. Check results against the acceptance criteria specified in Step 6 (Quality Checks).
5. Record all observations, measurements, and parameter readings in the plant log.
6. Notify the shift supervisor upon task completion and confirm handover.