

DAIKIN AIRCONDITIONING INDIA PVT. LTD.
Service Completion Certificate

Subject: Not working

Solutions Inc.

381 B.M Giri Nagar kalkaji / NEW DELHI 110019 / IN

Registration No.				Request Date		Service Engineer			Scheduled Date/Time		Service Order		
DEL0409201816235705				Sep 4, 2018		MR. Bablu			Sep 6, 2018		007005244983		
User: Lakshya flexi Tubes profiles Pvt. Ltd. Address: Lakshya flexi Tubes profiles Pvt. Ltd. / J-502 Tower / Noida 201301 / IN IBase Address: J-502, , 24, , Noida-, 201301, IN Daikin Invoice: Date: Dealer Invoice: Date: Type Model No Manufacturing No. Outdoor unit / Indoor unit RXYQ12PY1-I A000106												Fault Diagnosed	
												Power	Power Failure
													Phase Reverse
												PCB	In door unit PCB Defective
													Out door PCB Defective
												FM	In door unit Fan Motor Defective
													Outdoor Fan Motor Defective
												Comp	Comp. taking High Current / Amp
													Compressor Ground/ Earth
												Comp	Compressor Tripping due to High Temprature
													Compressor tripping due to High Pressure
												Indoor	Indoor Unit MgSw Defective
													Out door Unit MgSw Defective
												Unit	Indoor Unit Transformer Faulty
													Out door Unit Transformer Faulty
												Electrical	Fault of swing Motor
													Defcet of Drain Pump
												Unit	Expansion Valve Body / Motor Defective
													Defective Temperature Sensor of Indoor Unit
												Installation	Defective Temperature Sensor of Out door Unit
													Defective Current Sensor In Out door Unit
												Other	Gas Leakage at Indoor unit
													Gas Leakage at Outdoor unit
												Other	Blower broken
													Short Cycling of Air at Indoor Unit
												Other	Short Cycling of Air at Out door Unit
													Defect in Drain piping System
												Other	Gas Leakage from Flare nut
													Error in Transmission wiring
												Other	Product under capacity
													Rat bite case
												Other	Less cooling problem due to dirty Airfilter
													Remote setting changed
												Other	Clogged Condenser
													Other- Pl. specify
												Details of Repair Work Done	
Compressor manufacturing No. Defective Compressor Replacement Compressor Installed date Warranty AMC Using with Fault location Phenomena code Error code Oct 12, 2009 Yes / No Yes / No Yes / No Yes / No												Customer Impression about Service (Please rate on scale of 1 poor, 2 , 3 , 4 & 5 excellent) How is the behavior of visted engineer What is the level of your satisfaction How is the explaination by Engineer	
												a Simple Repair	
												b Part Replaced	
												c Part Repaired	
												d Gas Charging done	
												e Routine Service - Wet	
												f Routine Service - DRY	