File No: EX/22(NA/609)

May 2001

NATIONAL INDUSTRIAL CHEMICALS NOTIFICATION AND ASSESSMENT SCHEME

FULL PUBLIC REPORT

NE-8963H

This Assessment has been compiled in accordance with the provisions of the *Industrial Chemicals* (Notification and Assessment) Act 1989 (the Act) and Regulations. This legislation is an Act of the Commonwealth of Australia. The National Industrial Chemicals Notification and Assessment Scheme (NICNAS) is administered by the National Occupational Health and Safety Commission which also conducts the occupational health & safety assessment. The assessment of environmental hazard is conducted by the Department of the Environment and the assessment of public health is conducted by the Department of Health and Aged Care.

For the purposes of subsection 78(1) of the Act, copies of this full public report may be inspected by the public at the Library, National Occupational Health and Safety Commission, 92-94 Parramatta Road, Camperdown NSW 2050, between the following hours:

Monday - Wednesday
Thursday
Friday

8.30 am - 5.00 pm
8.30 am - 8.00 pm
8.30 am - 5.00 pm

Copies of this full public report may also be requested, free of charge, by contacting the Administration Coordinator on the fax number below.

For enquiries please contact the Administration Coordinator at:

Street Address: 92 Parramatta Rd Camperdown, NSW 2050, AUSTRALIA

Postal Address: GPO Box 58, Sydney 2001, AUSTRALIA Telephone: (61) (02) 9577-9514 FAX (61) (02) 9577-9465

Director Chemicals Notification and Assessment

FULL PUBLIC REPORT

NE-8963H

1. APPLICANT

First Applicant

An assessment certificate for the notified chemical, NE-8963H was granted to Minolta Business Equipment Australia Pty Ltd of 9/372 Eastern Valley Way CHATSWOOD NSW 2067.

The Assessment Report for NE-8963H is identified by the sequence number NA/609.

Second Applicant

Since granting of the abovementioned Assessment Certificate, Minolta-QMS Australia of 4-44 Hampden Road ARTARMON NSW 2154, Prion Technologies Pty Ltd of 3 Talavera Road NORTH RYDE NSW 2113, Tech Pacific Australia Pty Ltd of 55 Mentomore Avenue ROSEBERRY NSW 2018 and Computer Hardware of Australia Pty Ltd of 7-9 Harper Street ABBOTSFORD VIC 3067 have submitted a notification statement in support of their application for an extension of the Assessment Certificate for NE-8963H.

Minolta Business Equipment Australia Pty Ltd has agreed to this extension.

Some new information on the new chemical has been submitted by Minolta-QMS Australia, Prion Technologies Pty Ltd, Tech Pacific Australia Pty Ltd, Computer Hardware of Australia Pty Ltd since the original notification statement submitted by Minolta Business Equipment Australia Pty Ltd in matters affecting volume, concentration and packaging. These have lead to slight modifications to the occupational exposure and occupational health and safety effects sections. The original assessment report (NA/609) is reproduced here with amendments for the record as EX/22 (NA/609).

2. IDENTITY OF THE CHEMICAL

Claims were made and accepted for the identity of NE-8963H to be exempt from publication in the Full Public Report. The data items were:

chemical name other names CAS number molecular and structural formulae
molecular weight
spectral data
purity
identity of toxic or hazardous impurities
weight percentage of toxic or hazardous impurities
non-hazardous impurities
identity of additives/adjuvants
weight percentage of additives/adjuvants
polymer constituents
use and import volume

NE-8963H is not considered to be hazardous based on the nature of the chemical and the data provided.

Trade Name: NE-8963H

Number-Average 2 240

Molecular Weight (NAMW):

Maximum Percentage of Low Molecular Weight Species

Molecular Weight < 500: 5.88 Molecular Weight < 1 000: 12.76

3. PHYSICAL AND CHEMICAL PROPERTIES

Appearance at 20°C pale yellow powder

and 101.3 kPa:

Melting Point: 142.0 to 155.0°C (softening point)

60.3°C (glass transition point) (non-standard test, non-GLP)

Density: 1.185 (non-standard test, non-GLP)

Vapour Pressure: 1.7X10⁻⁷ Pa at 25°C - vapour pressure balance method

(non-GLP) (European Economic Community (EEC),

1992)

Water Solubility: $< 0.35 \text{ mg.L}^{-1} \text{ at } 20^{\circ}\text{C \& pH} \sim 6.5 \text{ -}$

column elution method

(European Economic Community (EEC), 1992)

(Mullee DM and Bartlett AJ, 1997)

Partition Co-efficient

(n-octanol/water): not determined - see comment below

Hydrolysis as a Function not measured- see comment below

of pH:

Adsorption/Desorption: not determined - see comment below

Dissociation Constant: not measured - see comment below

Particle size: $< 150 (13.7\%) - 2000 \mu m$

5 - 15 μm (toner product)

Flash Point: not applicable

Flammability Limits: not flammable

Autoignition Temperature: not auto-flammable

Explosive Properties: non-explosive

Reactivity/Stability: no oxidising properties based on chemical structure and

experience in use

Polydispersity (M_w/M_n) : 13.65

Comments on Physico-Chemical Properties

Tests were performed according to OECD/EEC test guidelines at facilities complying with OECD Principles of Good Laboratory Practice (GLP), except where stated.

The water solubility has been determined spectrophotometrically to be less than 0.35 mg.L⁻¹ using the column elution method. This is presumed to be the limit of detection.

The polymer contains some ester linkages which could be expected to undergo hydrolysis under extreme pH conditions. However, due to the very low water solubility, this is unlikely in the environmental pH range of between 4 and 9.

The determination of partition coefficient and adsorption/desorption could not be undertaken as the notified polymer was determined to be insoluble in both n-octanol and water, and the HPLC methods employed are not applicable to polymeric materials. Due to its very low water solubility, the polymer is expected to become associated with the organic component of soils and sediments.

No dissociation constant data was provided as the notifier claims that it is not possible to measure, i.e. according to OECD TG 112, because there is no mode of chemical dissociation for this compound. However, as the polymer molecule may contain a low amount of carboxylic acid functionality, it would be expected to display weakly acidic properties. Also, the very low water solubility should preclude manifestation of the inherent weakly acidic nature of the polymer.

4. PURITY OF THE CHEMICAL

Degree of Purity: High

5. USE, VOLUME AND FORMULATION

Minolta Business Equipment Australia Pty Ltd

NE-8963H will not be manufactured in Australia. NE-8963H will be imported as a component of a formulated toner product ready for use in photocopying machines.

The notified polymer will constitute 52% of the imported toner product. Import volumes for the notified chemical are estimated to be less than 1 000 kg for the first year and expected to increase to approximately 4 000 kg over the following four years.

The toner bottles will be interchanged with spent ones in electrophotocopying machines, usually by office staff. The toner bottles are sealed and designed so that no release of the contents can occur till the shipping tape is removed.

Minolta-QMS Australia, Prion Technologies Pty Ltd, Tech Pacific Australia Pty Ltd, Computer Hardware of Australia Pty Ltd

The toner containing the notified chemical will be imported by the applicants for extension in cartridges containing 230-250g toner. The content of notified chemical in the toner will be approximately 50%. Import volumes for the notified chemical are expected to be less than 1 tonne per annum in the first year and more than 1 tonne per annum over the next 4 years.

6. OCCUPATIONAL EXPOSURE

Minolta Business Equipment Australia Pty Ltd

Toner products containing the notified polymer will be imported in the form of pre-packed bottles, each containing 450 g of toner (234 g of the notified polymer). Waterside, warehouse and transport workers are unlikely to be exposed to the notified polymer unless the packaging were breached.

Office workers and copier maintenance workers may be exposed to the notified polymer contained in the toner products during the operation and/or servicing of photocopier machines. The pre-packed toner bottles are sealed and worker exposure to the contained toner product will be controlled by the use of the replacement procedures recommended by the manufacturer. The toner bottles are designed so that no release of the contents can occur until the seal tape is removed. However, dermal or inhalation exposure may occur if the toner is accidentally spilt while replacing spent toner bottles. Spent toner bottles are expected to retain approximately 10 g of toner. When replenishing the toner, the operator fits the toner bottle into the machine then peels off the seal tape, which allows the transfer of toner contents to storage within the photocopy machine. The particle size of the notified polymer ranges from less than 150 to 2 000 μ m. The particle size of the toner product (5 to 15 μ m) has been provided in the MSDS. This is within the respirable size range. Given that the notified polymer contains 13.7 % of particle size less than 150 μ m, exposure to inspirable and respirable dust is possible. Contact with paper printed with toners containing the notified polymer will result in dermal exposure. However, as the notified chemical will be bound in

the structure of the paper such exposure would not result in transfer of the chemical to the skin.

Maintenance workers for photocopiers would experience more frequent contact with the notified chemical. The design of the toner bottles and the fact that the toner powder is separately located within the photocopy machines means that maintenance workers should not become overly contaminated with toner powder during machine servicing.

Minolta-QMS Australia, Prion Technologies Pty Ltd, Tech Pacific Australia Pty Ltd, Computer Hardware of Australia Pty Ltd

The toner containing the notified chemical will be imported by the applicants for Extension in cartridges containing up to 250g toner of which approximately 50% will be notified chemical. Due to containment in a cartridge and the lower content, exposure to workers handling the notified chemical introduced by the applicants for Extension is likely to be less than that by the original applicant.

7. PUBLIC EXPOSURE

The potential for public exposure to the notified polymer is anticipated to be low. Public exposure may arise through contact with dust particles during maintenance of the photocopiers or through contact with cured toner on photocopied papers. These are not regarded to be significant as in most cases (except for people employed for photocopying) photocopying is carried out infrequently. The packaging of the toner product in bottles will markedly reduce the potential for exposure to the notified polymer. The cured toner is bound strongly to the paper therefore the notified polymer is not expected to be dermally absorbed.

Residual toner in toner bottles will be disposed of together with spent toner bottles as office wastes. It is estimated that 18 to 90 kg of the notified polymer will be disposed of as uncured toner. Cured toners printed on paper are likely to be disposed of as domestic or office wastes. Public exposure from disposal is expected to be negligible.

8. ENVIRONMENTAL EXPOSURE

Release

The toner product containing the notified polymer is fixed to the paper following application, which offers little potential for release. When the copier requires more toner, the empty bottle is replaced. The exchange process is designed to minimise toner losses. The majority of empty bottles are expected to be disposed of with general office waste and placed into landfill where release of toner should occur only after destruction of the integrity of the bottle. The notifier estimates the amount of toner residue remaining in the bottle to be 5 to 10 g of the notified polymer.

The majority of the notified polymer will be associated with the toner, which is strongly bound to the paper. Its release will be associated with the fate of the waste paper.

The notifier claims that filters installed in the copiers prevent leakage to the outside of the

machine. Accidental spills will be collected and disposed of to landfill or incinerated.

Fate

Waste paper disposal is effected either through incineration, recycling or deposition into landfill. Incineration will destroy the compound with production of water vapour and carbon oxides.

The notifier has provided no data on the likely behaviour of the polymer during the paper recycling process. During such processes, waste paper is repulped using a variety of alkaline, dispersing and wetting agents, water emulsifiable organic solvents and bleaches. These agents enhance fibre separation, ink detachment from the fibres, pulp brightness and the whiteness of paper. It is expected that during this process the material will be either destroyed chemically or, if it survives, be incorporated into waste sludge due to its low solubility. Waste sludge from the recycling plants will be either incinerated or disposed of to landfill, while aqueous waste will be comprehensively treated before discharge.

Some waste paper may be disposed of directly to landfill, and it is anticipated that prolonged residence in an active landfill environment will eventually degrade the notified substance. The same considerations will apply to waste sludge from paper recycling if disposed of to landfill.

Toner products containing the notified polymer (either from a spillage during toner bottle replacement or as residue in toner bottles) will be disposed of to landfill or by incineration. Leaching of the polymer from landfill is unlikely from these sites, given the low solubility of the substance. Hydrolysis, although theoretically possible, is unlikely.

Should the polymer be spilt into waterways, it is not expected to disperse into the water column, but settle out into sediments. The polymer is not expected to cross biological membranes, due to the low solubility and high molecular weight, and as such should not bioaccumulate (Connell DW, 1989).

9. EVALUATION OF TOXICOLOGICAL DATA

9.1 Acute Toxicity

NE-8963H has been notified under a limited notification category. According to the Act, no toxicological data are required under the limited notification; however, the notifier has provided results of a number of toxicological tests, which are summarised below. The tests were performed on the toner product, containing 52% of the notified polymer, NE-8963H.

Summary of acute toxicity

Test	Species	Outcome	Reference
acute oral toxicity	Rat	> 2 000 mg.kg-1	(Sanders A,

			1996)
skin sensitisation	guinea pig	non-sensitiser	(Sanders A, 1997)

9.1.1 Oral Toxicity (Sanders A, 1996)

Species/strain: rat/Sprague-Dawley Crl:CD®BR

Number/sex of animals: 5/sex

Observation period: 14 days

Method of administration: single dose of 2 000 mg.kg⁻¹ administered by

gavage in arachis oil

Clinical observations: no signs of systemic toxicity observed

Mortality: nil

Morphological findings: none

Test method: similar to OECD guidelines (European Economic

Community (EEC), 1993c)

 LD_{50} : $> 2~000~\text{mg.kg}^{-1}$

Result: the test material was of very low acute oral toxicity

in rats

9.1.2 Skin Sensitisation (Sanders A, 1997)

Species/strain: guinea pig/Dunkin Hartley

Number of animals: 30/unspecified (20 tests; 10 controls)

Induction procedure: Test

Day 0:

- 50 % concentration of test material in 80% aqueous ethanol applied to the left flank of each test animal by occlusive dressing
- patch was held by surgical adhesive tape and covered with aluminium foil
- occlusive dressing was removed after 6 hours and test sites decontaminated using diethyl ether

Day 7 and 14:

• similar dose as on day 0 applied to the same test area

Control

similar topical application procedure using 80% aqueous ethanol alone

Challenge procedure:

Day 28:

- 50 % (w/w) concentration of test material in 80% aqueous ethanol applied to the left flank of test and control animals by occlusive dressing
- 25% (w/w) concentration of test material in 80% aqueous ethanol also was applied to the right flank of test and control animals by occlusive dressing
- patches were held by surgical adhesive tape and covered with aluminium foil
- occlusive dressing was removed after 6 hours and test sites decontaminated using diethyl ether

challenge was evaluated at 24 and 48 hours after dressing removal

Challenge outcome:

	Test animals		Control animals	
Challenge concentration	24 hours*	48 hours*	24 hours	48 hours
25%	**0/20	0/20	0/10	0/10
50%	0/20	0/20	0/10	0/10

^{*} time after patch removal

Test method: similar to OECD guidelines (European Economic

Community (EEC), 1993b)

Result: the test material was not a skin sensitiser in guinea

pigs

9.3 Genotoxicity

^{**} number of animals exhibiting positive response

9.3.1 Salmonella typhimurium and Escherichia coli Reverse Mutation Assay (Thompson, 1993)

Strains: Salmonella typhimurium TA1535, TA100,

TA1537, TA1538, TA98 Eschericia coli WP2uvrA

Concentration range: 0, 50, 150, 500, 1 500 and 5 000 µg.plate⁻¹ with or

without metabolic activation (rat liver S9 mix)

Test method: similar to OECD guidelines (European Economic

Community (EEC), 1993d), (European Economic

Community (EEC), 1993a)

Result: the test material was not mutagenic in the bacterial

strains tested in the presence or absence of

metabolic activation

9.4 Other data

The notifier summarised a literature study on chronic inhalation exposure to a commercial toner (Xerox 9000) in rats (Muhle et al, 1991). Nine hundred F - 344 rats of each sex were exposed by inhalation to the commercial toner with respirable size particles of 35% (respirable according ACGIH criteria) for 6 hours per day, 5 days per week for a period of 24 months. The extent of lung fibrosis increased with both duration and exposure to toner. The summary reports mild to moderate lung fibrosis was observed in 92% of rats at a dose of 16 mg/m³ (high dose). At 4 mg/m³ dose (mid dose), 22% of the animals had minimal to mild lung fibrosis. There was no pulmonary change observed at 1 mg/m³ dose (low dose). Muhle et al indicated that the low dose level was most relevant in regard to potential human exposures but did not explain the basis for this assertion. The authors also suggest that the lung alterations observed in high dose exposure were associated with chronic lung overloading, a generic response of the respiratory system to saturation of its detoxification capacity. The inhalation of the commercial toner and appropriate control materials did not show any signs of overt toxicity. NICNAS obtained the full study for the purposes of this assessment. The above summary is an accurate reflection of the adverse effects seen in the lungs of rats exposed to the commercial toner. Exposure to the toner did not result in an increased frequency of lung tumours, compared with the air only and titanium oxide control groups.

9.5 Overall Assessment of Toxicological Data

There is only limited toxicological data submitted for the notified polymer, NE-8963H. This is acceptable under the requirements for a limited notification. All tests were performed on the toner preparation, which contains 52% of the notified polymer. The product exhibited very low oral acute toxicity in rats with an LD₅₀ greater than 2 000 mg.kg⁻¹. Acute dermal or inhalation toxicity data was not provided for the product. Skin and eye irritation data were also not provided. The product was not a skin sensitiser when tested

using a modified Buehler test in guinea pigs. The product was found to be not mutagenic when tested in a bacterial reverse mutation assay.

The toner product containing 52% of the notified polymer would not be classified as hazardous according to the NOHSC Approved Criteria (National Occupational Health and Safety Commission, 1994a), considering only the toxicology information provided by the notifier.

The 24-months inhalation study of a commercial toner (Xerox 9000) with respirable size particles of 35% (respirable according ACGIH criteria), in rat by Muhle at al (1991) indicated that the lowest dose where lung fibrosis was seen was 4 mg/m³. There was no pulmonary change observed in animals treated with 1 mg/m³. The authors also suggest that lung alterations observed in high dose exposure were associated with chronic lung overloading, which is a generic response of the respiratory system to saturation of its detoxification capacity. The inhalation of the commercial toner did not result in any signs of overt toxicity or increased frequency of lung tumours, when compared to the appropriate control animals.

10. ASSESSMENT OF ENVIRONMENTAL EFFECTS

No ecotoxicology data were provided, which is acceptable for polymers of NAMW > 1000 according to the Act.

11. ASSESSMENT OF ENVIRONMENTAL HAZARD

The majority of notified polymer should not enter the environment until it is incorporated into a polymer matrix when the toner is cured and fixed to paper. Disposal of the waste paper containing the cured toner is normally through landfill, incineration or recycling. In all three cases it is anticipated that the polymer will be destroyed either through the agency of a vigorous chemical environment, or through slow biological or abiotic processes. Even without substantial degradation, the diffuse nature of disposal patterns would indicate slow release into the wider environment.

Accidental spillage of the toner, either during filling of toner hoppers or during transport, should result in powder wastes being sent to either landfill or incineration facilities. Empty bottles containing residues of toner are also likely to be sent to landfill or for incineration. Movement of the polymer by leaching from landfill sites is not expected.

Considering the above, environmental exposure and the overall environmental hazard is expected to be low.

12. ASSESSMENT OF PUBLIC AND OCCUPATIONAL HEALTH AND SAFETY EFFECTS

Minolta Business Equipment Australia Pty Ltd

Waterside, warehouse and transport workers will only be exposed to the notified polymer in the event of an accident or damage to packaging. The occupational health risk to these workers is negligible, particularly considering the physico-chemical properties of the notified chemical and the low hazard presented by the toner product containing the notified polymer.

Office workers may need to handle the notified chemical within the container when replacing the spent toner powder. The design of the toner bottles is such that exposure to the notified polymer should be minimal when undertaking this task; however, some dermal or inhalation exposure may occur if toner is accidentally spilt. Maintenance workers regularly servicing office machines may frequently come in contact with small amounts of residual toner. In general however, the separate location of toner and the design of toner bottles should control incidental contact. Should either office workers or maintenance workers come into contact with the toner product or notified polymer, the risk of adverse health effects is low. Firstly, the chemical has a large molecular weight, therefore absorption across biological membranes would be limited. The toner product containing the notified polymer was not a skin sensitiser when tested using a modified Buehler test in guinea pigs. There may be low levels of toner dust in the immediate vicinity of photocopy machines when the machines are operating. Inhalation of the notified chemical (with 13.7 % of particle size less than 150µm) is possible but is expected to be minimal. Separate transfer of the notified polymer from paper to the skin is not expected to occur once the toner is bound in the structure of the paper after the copying process.

The notifier submitted a summary of a 24-month study of chronic inhalation exposure to commercial toner (Xerox 9000) containing 35% of particles of respirable size (respirable according ACGIH criteria), in rats (Muhle et al, 1991). The summary provided indicates that 92 % of rats had mild to moderate lung fibrosis at 16 mg/m³ dose (high dose) and 22% had minimal to mild lung fibrosis at 4 mg/m³ dose (mid dose). There was no pulmonary change observed at 1 mg/m³ dose (low dose). Muhle et al indicated that the low dose level was most relevant in regard to potential human exposures but did not provide the basis for assertion. The authors also suggest that the lung alterations observed in high dose exposure were associated with chronic lung overloading, a generic response of the respiratory system to saturation of its detoxification capacity. The inhalation of the commercial toner did not produce signs of overt toxicity or increased frequency of lung tumours outside the control values.

Consequently, based on the low toxicological hazard presented by the chemical and the expected minimal exposure, the health risk posed to office workers and maintenance workers by the notified polymer is low.

Some toxicological data was provided in the MSDS for the toner product containing the notified polymer. Carbon black is present in the toner product at a concentration of 1 to 5 %. Should the toner product be formulated in Australia, employers will need to ensure that the exposure standard for carbon black of 3 mg/m³ (TWA) (National Occupational Health and Safety Commission, 1995) is not exceeded. Photocopy machines should be located in well-ventilated areas. It is unlikely that exposure monitoring would be necessary in the normal office environment.

Minimal public exposure is expected to occur during transport, handling or use, or from disposal. The general public may come in contact with cured toner on photocopied paper. However, the cured toner is bound strongly to the paper and the notified polymer is not expected to be dermally absorbed.

Minolta-QMS Australia, Prion Technologies Pty Ltd, Tech Pacific Australia Pty Ltd, Computer Hardware of Australia Pty Ltd:

The toner imported by the applicants for Extension will be contained within photocopier cartridges and will contain approximately 50% notified chemical. Due to containment in a cartridge and the lower percentage content, exposure and therefore risk to workers handling the notified chemical introduced by the applicants for Extension is likely to be less than that by the original applicant.

13. RECOMMENDATIONS

To minimise occupational exposure to NE-8963H the following guidelines and precautions should be observed:

- Work areas around the photocopy machines should be well ventilated. Workers using the product should implement good work practices to avoid spillage or the generation of dusts;
- Spillages should be cleaned up promptly and placed into containers for disposal;
- Good personal hygiene should be practised to minimise the potential for ingestion; and
- A copy of the Material Safety Data Sheet (MSDS) for NE-8963H and/or information about the toners containing NE-8963H should be easily accessible to employees.

Employers need to ensure that the exposure standard for carbon black of 3 mg/m³ (TWA) (National Occupational Health and Safety Commission, 1995), which is a component of the toner product, is not exceeded in the workplace.

14. MATERIAL SAFETY DATA SHEET

The MSDS for the product containing the notified chemical was provided in a format consistent with the *National Code of Practice for the Preparation of Material Safety Data Sheets* (National Occupational Health and Safety Commission, 1994b).

The MSDS was provided by the applicant as part of the notification statement. It is reproduced here as a matter of public record. The accuracy of this information remains the responsibility of the applicant.

15. REQUIREMENTS FOR SECONDARY NOTIFICATION

Under the Act, secondary notification of the notified chemical shall be required if any of the circumstances stipulated under subsection 64(2) of the Act arise. No other specific conditions are prescribed.

16. REFERENCES

Connell DW (1989) General Characteristics of Organic Compounds Which Exhibit Bioaccumulation. In: D. W. Connell ed. Bioaccumulation of Xenobiotic Compounds. CRC Press, Boca Raton.

European Economic Community (EEC) (1992) Methods for the Determination of Physico-Chemical Properties. In: ed. EEC Directive 92/69, Annex V, Part A, EEC Publication No. L383. EEC.

European Economic Community (EEC) (1993a) Method for the Determination of Toxicty, Part B.13 Mutagenicity (*Escherichia coli* - Reverse mutation assay). In: ed. EEC Directive 92/69, Annex V, Part B. EEC.

European Economic Community (EEC) (1993b) Methods for the Determination of Toxicity, Part B.6 Skin sensitisation. In: ed. EEC Directive 92/69, Annex V, Part B. EEC.

European Economic Community (EEC) (1993c) Methods for the Determination of Toxicity, Part B.1 Acute toxicity (oral). In: ed. EEC Directive 92/69, Annex V, Part B. EEC.

European Economic Community (EEC) (1993d) Methods for the Determination of Toxicity, Part B.14 Mutagenicity (*Salmonella typhimurium*-Reverse mutation assay). In: ed. EEC Directive 92/69, Annex V, Part B. EEC.

Muhle B, Bellmann B, Creutzenberg O, Dasenbrock C, Ernst H, Kilpper R, MacKenzie JC, Morrow P, Mohr U, Taneks S and Mermelstein R (1991) Pulmonary Response to Toner upon Chronic Inhalation Exposure in Rats, Fundamental and Applied Toxicology, 17, 280-299.

Mullee DM and Bartlett AJ (1997) Determination of General Physico-Chemical Properties, Project No. 635/063, SafePharm Laboratories Ltd, Derby UK.

National Occupational Health and Safety Commission (1994a) Approved Criteria for Classifying Hazardous Substances [NOHSC:1008(1994)]. Australian Government Publishing Service, Canberra.

National Occupational Health and Safety Commission (1994b) National Code of Practice for the Preparation of Material Safety Data Sheets [NOHSC:2011(1994)]. Australian Government Publishing Service, Canberra.

National Occupational Health and Safety Commission (1995) National Exposure Standards for Atmospheric Contaminants in the Occupational Environment, [NOHSC:1003(1995)]. In: ed. Exposure Standards for Atmospheric Contaminants in the Occupational Environment: Guidance Note and National Exposure Standards. Australian Government Publishing Service, Canberra.

Sanders A (1996) M-36 II Toner: Acute Oral Toxicity (Limit Test) in the Rat, Project No. 635/054, Safepharm Laboratories Limited, Derby, UK.

Sanders A (1997) M-36 II Toner (A): Buehler Delayed Contact Hypersensitivity Study in the Guinea Pig, Project No. 635/057, Safepharm Laboratories Limited, Derby, UK.

Thompson P (1993) LR-147: Reverse Mutation Assay 'Ames Test' Using *Salmonella typhimurium* and *Escherichia coli*, Project No. 256/53, Safepharm Laboratories Limited, UK.