



RMA Shipping Instructions

1. Please clean the equipment properly before sending for Repair.
2. Clearly label all boxes with FASTECH shipping address and your RMA Numbers.
3. **Address to ship RMA for Repair / Calibration.**

**Fastech Telecommunications (India) Pvt. Ltd.,
Fastech PARAM
EL-44, Electronic Zone,
TTC Industrial Are, MIDC, Mahape,
Navi Mumbai – 400710
Contact Person: Mr. Krishna Ch Raulo
Tel. No. 022-28353636
GST No. 27AAACF4021B1ZE**
4. Please ship the instrument duly packed with bubble plastic in an appropriate thick cardboard carton.
5. Please clearly declare that the Kit is being returned for repairs/calibration and is of no commercial value.
6. Please ship this consignment to us duly insured.
7. Please dispatch the unit along with proper documentations (DC, PL and OGP) to the above address:
8. **Please DO NOT send power supplies, power cords, manuals, cables, SFPs, pouches or carrying cases with the units unless specified by Technical Support to do so. We are not responsible for these parts if you do send them with the unit without prior authorization.**
9. The freight, insurance and packing charges for sending the unit to FASTECH warehouse will be borne by the customer. FASTECH will bear the freight and packing charges for sending the calibrated unit to customer's designated place (PAN India) if the unit is under warranty/AMC. Additional charges if any will be borne by the customer.
10. If we do not receive the equipment at our warehouse within 30 days from the date of issue of RMA then we shall close the RMA.

Please provide the courier details with airway bill no. and date of dispatch to service@fastech-india.com or Fax #:022 28367765.