	Н	MSI-	4F				SH	IIFT RI	PORT	FRAM	E BOD	Υ		Forma	t No	07020)-WE4	F-F2-0	123		
	la.		1		1:	M	· damma	or Dotaile			Line wise		S Observation				Action Taken				
	Item		L1		L	<u>LI</u> 2		e wise Manpowe WBS		AMT	Total		Line wise	Observation				Action Taken			
ft							55		CKD												
	Plan	M.P	40				43				8	83 L1		vbjkb			fbdb				
	(On roll)																				
	Present																				
			41				43				84										
													L2	biubgfew			fewg				
		P										0									
A shift																					
A	Absent																				
		U								(0 WBS										
											0										
		Т											CKD								
	ОТ	HRS									()	AMT								
														O Br. D. I.I.					D	- I I a I al-	
	ite	em	QG -2 Return Qty.		Total	Offline	e Rework Qty.	Total			nline Rework %				Quality Problems: Rewor					Kewon	(Hola:
-			Noturi	ı Qıy.			ery.	у.	LH	RH LH		RH	Max.	AF & PA:							
0	L1											\leq	0								
		,			0			0					0	BOP:							
		.2																			
							Model				D-Production			Ι		Mod	iel - CBU	l			
			Details	KOP	KOL	K0Y	Model K1J	KZK	K24	То	tai	SPD	Inventory	KOP	KOL	K0Y	lel - CBU K1J	KZK	K24	Total	SPD
		L1	P							()		CBU							_	
			A						(`		Inventory Shift Start							0		
				-										_							
			P							()		CKD Inventory							0	
		L2	Α							()										
	Frame body			-									CBU ACED							0	
			P							()		loading								
	Fra	CKD	Α							(
													CKD Loading							0	
			Р							()										
		BS4	Α	A						()		CBU								
۵													Inventory							0	
		Total	Р	0	0	0	0	0	0	()		Shift End								
		မ	Α	0	0	0	0	0	o	()		CKD Inventory							0	
-		De	tails	KZK	CKD	CBU		K24		То	tal	SPD	invencery	Inv	entory			KZK	K24	Total	SPD
			Р											Shift Start					0		
		Front		-									Front		Stillt Start					_	
			Α							()			Shift End					0		
	<u>e</u>		Р	,					()			Shift Start					0			
	Export Line	Rear											Rear								
	Ä		A							()				Shift End				0	%	
		Inspection		Front	Front Rear		3 -BS4	FB-	BS6		Total			Front	Rear	FB-	FB-BS4		BS6		Total
			P								0		CKD QG2								
		용											-Retrun							0	
			A								0			L							
L1:			Los	ses Det	ails & 4	IM Cor	mmunica	tion:						H	eadWise	Loss Su	mmary:				
											ACED		achine	JM		BOP/MS		STORE		IN HOUSE	
											ACLD	Maintenance		Maintenance		BOTTING		STORE		INTIOUSE	
L2:														D	ay - SPD	loading	Status				
												Parts		A shift				arts		A shift	R chif
BS4:												raiu	•	A SIIII	D SIIIIL		га	ir us		A SIIII	D SIIII
Oth																					
ers:																					
Report Date L1					L2			WBS CKD			UL SH										
A Shift																					
		1.3	3/05/202	5					l R	aiul Gupt	а	Te	ias san	1		I		1		I	

Digital Signatures					
Role	Name	Emp Code			
Prepared By	r	12289			
Prepared By	u1	12288			
Verified By	u	4556			
Approved By	Atul San	0000			