Work Report (period 1.5.2014 to 31.5.2014) by RRU

- 1. Compiled & tested USB-RS485 mcmtest program on Miltec PC. Successfully tested serial port communication on Miltec PC.
- 2. Worked with Shri Mangesh for antenna sub-net (21) network problem.
- 3. Installed MCMTEST USB-RS485 program on new PC for ABR Lab. Installed MCMTEST USB-RS485 program on correlator machine used by SCC for switching walsh bits.
- 4. Modified code in high_user.c & das.c so that it can generate proj.hdr & scan.hdr file.
- 5. Installed MCM cards at CO1, CO4, CO9 and C10.
- 6. Modified the mcmtest.c program USB-RS485 based so that post gain of IF system can be set.# Changing the position of ALC & Post gain setting worked.Successfully tested the SET_IF command in ABR Lab.
- 7. Modified Online_V2 code for perror so that error related to creating thread can be traced.
 This code will give some clue about what went wrong with thread creation.
- 8. Separated the mcm thread creation from main.c in a separate file mcm.c & mcm.h. MCM thread creation is done in mcmsystem function written in mcm.c.