


MIND MAPPING SP3S

SMART PORTABLE STOVE SAFETY SYSTEM



**SOFTWARE/
PROGRAMMING**

- Buggy Code
- Incorrect ADC Calibrations
- Failure to Handle AT-Commands
- Blocking Delays
- Loss of Data Synchronization
- Improper Threshold Settings

**HARDWARE/
COMPONENTS**

- Defective MQ-6 Sensor
- Malfunctioning Solenoid Valve
- Broken ESP8266
- LCD Failures
- Burned Components
- Power Surge

**MEASUREMENT/
SAMPLING**

- Incorrect Sensor Placement
- Inaccurate Temperature
- Reading (LM35)
- Sensor Drift
- Noisy Signals
- Sampling Rate Errors

**MANPOWER/
USER ISSUES**

- Incorrect Components Handling
- Poor Soldering
- Misinterpretation of Data
- Installation Errors
- Lack of Maintenance

**STOVE SAFETY
SYSTEM FAILURE/
RELIABILITY ISSUES**

- Circuit Theorors
- Incorrect ADC Sensrior
- Sensor Failunss
- Federal Handling
- Inaccurate Programmings

**SOFTWARE/
COAMPLING**

**MANPOWER/
SAMPLING**

- Incorect Component
- Stose Components
- Web Aplication
- Load Out Sctings
- Alarm

**MATERIAL/
INPUTS**

- High Gas Concentrations (false alarms)
- Fluctating Temperature (false alarms)
- External Interference
- Low Signal Strenght (Wifi)
- Quality Variations Of Parts

**ENVIRONMENT/
CONDITIOS**

- Extreme Heat (Stove)
- High Humidity
- Dust Accumulation on Sensors
- Physical Vibration
- Unstable Wifi Connectivity

**STOVE SAFETY
SYSTEM FAILURE/
RELIABILITY ISSUES**