

⑧

2000H ← ch
2001H }
~~2000H~~ }
42A, M 200AH }

LXI H, 2000H 2100^a 21
MOV B, ~~M~~ 2101 00
MOV A, B 2102 20
~~MOV B, M~~ 2103 46
CPI @41H 2104

J2 case-A 2105

J2 case-B 2108

9
A

~~INX H~~

~~MVIM~~

MVIM M, 49H

~~INX H~~

MVIM M, 49H

~~INX H~~

MVIM M, 45H

~~INX H~~

MVIM M, 53H

~~INX H~~

MVIM M, 54H

~~INX H~~

MVIM M, 53H

JMP End

~~INX H~~

MVIM M, 41H

~~INX H~~

MVIM M, 52H

~~INX H~~

~~MVIM~~

~~INX H~~

MVIM M, 43H

~~INX H~~

MVIM M, 48H

JMP End

~~INX H~~

MVIM M, 43H

~~INX H~~

MVIM M, 53H

~~INX H~~

MVIM M, 54H

End

RST 5