

(6)

LXI H, 2000H

2100 21

2101 00

2102 20

MOV B, M

2103 46

INX H

2104 23

MOV C, M

2105 4E

MOV A, B

2106 78

ADD B

2107 80

CMPC

2108 B9

JC Make ~~505H~~

2109 DA

210A 11

210B 21

MVI D, ~~10H~~

210C 16

210D 10~~0~~


JMP End

210E C3

210F 13

2110 21

2111 16

2112 10~~0~~05MVI D, ~~50H~~

23

End

INX H

2113

MOV M,D

2114

72

RST 5

2115

EF