```
C =
 s^2 + s + 1
  -----
Continuous-time transfer function.
Model Properties
C =
 Kp + Ki * --- + Kd * s
 with Kp = 1, Ki = 1, Kd = 1
Continuous-time PID controller in parallel form.
Model Properties
Unrecognized function or variable 'P'.
Error in codecruisecontrol (line 19)
step(P);
>>
>> codecruisecontrol
 s^2 + s + 1
  -----
      S
Continuous-time transfer function.
Model Properties
T =
     100
 -----
 1000 s + 150
```

Continuous-time transfer function.

Model Properties

>>