===

[Errno -2] Name or service not known

===

Error occured in line number 218

Expected Result : 1. The status of the software slot used for software activation r

VALID (it is unchanged) and the parameter "active" remains "True". The para

"running" is set to True.

2. Status of the software slot containing the previous version of software use

device remains VALID, the parameter "active" remains False. The parameter "

is set to False.

===

  ***************** Actual Result *****************

===

===

****************** FAIL_REASON *******************

===

[Errno -2] Name or service not known

===

Supplemental Reset after Software Activation   =   FAIL

===