CMC Bio Filter Service

Service Date: 11 September 2025

Work Completed

Engineer attended site around 9/9.30am to extract and clean all pumps in the bio-filter and water pumping station.
Fence panel removed in the car park for access to the pumping water tank.
Primary tank booked for vacuum suction that week.
During the Autumn service pump number 2 was found not working.
The pump had been under surveillance as it was pulling too many amps.
Pump number 2 replaced and all systems working efficiently.

System Status

All systems confirmed working efficiently following replacement of pump number 2.

Costs

Service Maintenance £625.00
Replacement pump £320.00 includes 1yr warranty
Labour for replacing new pump £300.00
Total Cost £1245.00

Payment to

Christine McCann
Sort code: 60-84-07
Acc No: 96324432

Engineer

Manny