RJ Beckett

Roofing & Building Maintenance

~~Estimate~~ / Invoice

Address:
Farmhouse
- The Courtyard
Liscombe Park
LU7 0GY.

Date: 18/8/21

Ref: The Courtyard Management Company LTD

Description Roof repairs;

1. Supply and fit roof tiles to main roof elevations as instructed.
2. Re-bed and wall rear roof valley using Sand and Cement mortar / Ali trim.
3. Re-fit, replace and reseal low level lead flashings.
4. Clear away all debris leaving premises clean and tidy.

Cost £500 = + V.A.T. @ 20%
Total Cost £600 = INC V.A.T. (£100 =).

Please use these details for payment; Lloyds Bank (R.J. Beckett). Acc no 01419568 Sort Co 772116.

Many Thanks

R.J. Beckett.

2A Digby Road Leighton Buzzard
Beds • LU7 1BX
Tel: 01525 377 816
Mobile: 07767 302 381
info@rjbeckettroofing.co.uk

VAT No: 935 7337 01

Your Local Man!