



Non-Ideal Turbines

What is the main cause that turbines are not ideal?

Answer: Steam flowing past the turbine blades

Explanation: Most energy is lost because the steam flows past the turbine blades, thus not converting its kinetic energy in rotational energy of the blades.