



#	Part Number	Description	lb	Qty	Each
01	32 72 2 333 503	HANDBRAKE LEVER WITH INTEGRAL ABS (to 06/01)	1.37	1	\$704.58
01	32 72 7 710 201	CONTROL ASSEM, BRAKE SYST., INTEGRAL ABS (from 06/01)	0.90	1	\$704.58
FO	R VEHICLES WIT	TH SPECIAL MODEL R1150RT SAPHIRE B	LACK (CODE:	X360A) :
01	32 72 7 710 198	CONTROL ASSEM, BRAKE SYST., INTEGRAL ABS	1.53	1	NA 🖹
ON	LY FOR REPAIR	AT THE DEALERS :			
02	71 60 7 654 754	HANDBRAKE LEVER, CHROME	0.36	1	\$179.00
۵	42 P				
02	71 60 7 654 754	HANDBRAKE LEVER, CHROME (to 06/01)	0.36	1	\$179.00
٥	43				
02	32 72 7 682 812	HANDBRAKE LEVER, CHROME (from 06/01)	0.32	1	\$212.20
02	32 72 2 332 896	HANDBRAKE LEVER, BLACK (to 06/01)	0.34	1	NA



ONLY APPLIES TO	ONLY APPL:	IES TO
-----------------	------------	--------

	32 72 2 333 503	HANDBRAKE LEVER WITH INTEGRAL ABS (to 06/01)	1.37	Х	\$704.58
	32 72 7 650 773	HANDBRAKE LEVER (to 06/01)	1.36	Х	\$704.58
02	32 72 7 657 148	HANDBRAKE LEVER, BLACK (from 06/01)	0.31	1	\$163.21 🟋
ON	LY APPLIES TO	:			
	32 72 7 657 182	HANDRRAKE LEVER (from 06/01)	1 34	Υ	¢600 74 🗺

32727665864 was superseded by 32727710201.

FOR VEHICLES WITH SPECIAL MODEL R1150RT SAPHIRE BLACK (CODE: X360A) ONLY FOR REPAIR AT THE DEALERS:

02 **32 72 7 682 812** HANDBRAKE LEVER, CHROME 0.32 1 \$212.20

NOT FOR VEHICLES WITH HEATED HANDLEBAR GRIPS (CODE: X519A) :

03 **61 31 7 709 512** RIGHT GROOVED HANDLE 0.18 1 \$143.63



FOR VEHICLES WITH ROTARY GRIP BRAKE (CODE: X532A) :

03 **32 72 7 659 646** RIGHT GROOVED HANDLE 0.19 1 **NA**

FOR VEHICLES WITH HEATED HANDLEBAR GRIPS (CODE: X519A) :

03 **61 31 7 710 440** RIGHT GROOVED HANDLE 218.92 1 \$239.37







FOR VEHICLES WITH HEATED HANDLEBAR GRIPS (CODE: X519A) AND ROTARY GRIP

BRAKE (CODE: X532A):

03 61 31 7 671 604 RIGHT GROOVED HANDLE 0.25 1 \$239.37

NOT FOR VEHICLES WITH HEATED HANDLEBAR GRIPS (CODE: X519A) :

04 **32 72 7 658 470** HANDLE RIGHT 0.17 1 NA

FOR VEHICLES WITH HEATED HANDLEBAR GRIPS (CODE: X519A) :

04 61 31 2 306 232 HANDLE RIGHT 196.17 1 \$239.37