
deadzone
idle
thrust
F_F
0
F_R
requested thrust


D_g
gear
F
N
R
time step