
deadzone
idle
thrust
F_{idle}
0
$-F_{\text{idle}}$
requested thrust
D_g
gear
F
N
R
ignored
time step