
deadzone
idle
$F_{\text{idle}}$
0
$-F_{\text{idle}}$
thrust
requested thrust


$D_g$
F
N
R
gear
ignored
time step