

Dwyer R&D, Inc. 30405 SE 84th St., #267 Preston, WA 98050 206-851-6595 dwyerrandd@comcast.net

BILL TORPI Inc.
3325 S. 116th St., Suite 161

Seattle, WA 98168

SHIP TO RPI Inc. 3325 S. 116th St., Suite 161 Seattle, WA 98168 Invoice 1099

DATE 05/29/2019 **TERMS** Net 30

DUE DATE 06/28/2019

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
05/17/2019	Service/Repair	Prism 78 Machine not cycling, all voltages OK. A couple of relays in the wrong position. Replaced NC contactor on right button. Good working order.	3	96.00	288.00T
05/17/2019	Mileage		60	0.39	23.40T
05/23/2019	Service/Repair	Checked all cam switched, machine not cycling. Cleaned 12 volt contacts, machine up and running.	3	96.00	288.00T
05/23/2019	Mileage		60	0.39	23.40T
05/24/2019	Service/Repair	Problem persists, found short knife. Knife is too close to knife latch. Corrected problem. Good working order.	2	0.00	0.00
		SUBTOTAL			622.80
		TAX			62.28
		TOTAL			685.08
		TOTAL DUE			\$685.08